APPENDIX C
CRS FORMS

					-
					_
					_ =
					4.4 13
			. :	:	-
				<i>:</i>	, -
				•••	
					-
			•		—
				; `	-
			•		÷
			· ·		
					• • • • • • • • • • • • • • • • • • •
					<del>_</del>
		All the second s			
					- - -
				•	_
					— <u>i</u> -
					·
	Andrew States				
	•		.; .;		
					· <b></b>
				,	_

## CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

1.	HISTORIC NAME/FUNCTION:	Dwelling, 116	6 Church F	Road			
2.	ADDRESS/LOCATION: 1166 Church Road (West Side)						
3.	TOWN/NEAREST TOWN: Bear						vicinity? 🖂
4.	MAIN TYPE OF RESOURCE:	building landscape		structure district		site 🗌	object 🗌
5.	MAIN FUNCTION OF PROPERTY	: _ Dwellir	ng				
6.	5. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Church Road (Wynnefield to S.R. 71) Improvements						
7	7. ADDITIONAL FORMS USED:						
	#: Form:		List prope	rty types:			
	1 CRS 2 Main Building Form	1	Dwelling	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>			
	1 CRS 3 Secondary Building		Barn				
	0 CRS 4 Archaeological Site						
	0 CRS 5 Structure (Building						
	0 CRS 6 Structure (Land Fea						
	0 CRS 7 Object Form						
	0 CRS 8 Landscape Element	ts Form		_			
	1 CRS 9 Map Form		N/A				
	0 CRS 14 Potential District F	Form					
8. :	SURVEYOR INFORMATION:						
	Surveyor name:	Gerald M. F	Cuncio				
	Principal Investigator name:	_Geratd M. F	Cuncio				
	Principal Investigator signature:						
	Organization:	Skeily and	Loy, Inc.	_		Date	e: <u>9/2/2003</u>

Dwelling constructed d	uring the post-World War II	era	
STATE HISTORIC CONT	FYT FRAMEWORK (check :	ill appropriate boxes; refer to state m	anagement
an(\$)):	EXT I MAINEWORK (Elleck C	in appropriate boxes, refer to state in	anagement
a) Time period(s)	☐ Pre-European Co ☐ Paleo-Indian	ontact	
	Archaic Woodland I		
	☐ Woodland II		
	1600-1750± Contact Period 1630-1730± Exploration an		
	1730-1770± Intensified and 1770-1830± Early Industria	l Durable Occupation	
Ä	1830-1880± Industrializatio	n and Early Urbanization	
	1880-1940± Urbanization a 1940-1960± Suburbanization	nd Early Suburbanization on and Early Ex-urbanization	
b) Geographical zone	☐ Piedmont		
		insula insula/Cypress Swamp	
	Coastal	y of Wilmington)	
a) Lintaria asstad these		y or williamigroup	
c) Historic period them			
	Agriculture Forestry	<ul> <li>☐ Transportation and Communical</li> <li>☐ Settlement Patterns and Demog</li> </ul>	
	Trapping/Hunting Mining/Quarrying	<ul> <li>☐ Architecture, Engineering and D</li> <li>☐ Government</li> </ul>	ecorative Arts
	Fishing/Oystering Manufacturing	Religion Education	
	Retailing/Wholesaling	Community Organizations	
	Finance Professional Services	<ul> <li>Occupational Organizations</li> <li>Major Families, Individuals and</li> </ul>	Events
			4
	ŲSE BLACK	INK ONLY	crs-1

CRS# N-14133

9. OTHER NOTES OR OBSERVATIONS:

## CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-14133

	~~~
1.	ADDRESS/LOCATION: _1166 Church Road
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling
3.	YEAR BUILT: 1949 CIRCA?: ARCHITECT/BUILDER: Unknown
4.	STYLE OR FLOOR PLAN: Post-World War II vernacular
5.	INTEGRITY: original site ⊠ moved □
	if moved, from where other location's CRS # year
	list major alterations and additions with years (if known)  a. b.
6.	CURRENT CONDITION: excellent  good  fair poor
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	<ul> <li>a. Overall shape: L-shaped with addition on north Stories: 1 1/2 side</li> <li>Additions: 1-Story addition on north side</li> </ul>
	b Structural system (if known): Balloon frame
	c. Foundation: materials: Poured concrete basement: full ⊠ partial □ not visible □ no basement □
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding
	e. Roof: shape: Cross gable materials: Asphalt shingle cornice: Open dormers: None chimney: location(s): Brick exterior; north side of main block
8.	DESCRIPTION OF ELEVATIONS:
	<ul> <li>a. Facade: Direction: E</li> <li>1) Bays 3; south end has cross gable roof and extends slightly</li> <li>2) Windows 5 fenestration Symmetrical type Plate glass picture window w/ 1/1 sidelights; paired 1/1 vinyl sash trim Plain board surrounds shutters None</li> </ul>

```
Facade (cont'd)
          Door(s)
                         1
             location
                         Centered
                         Raised panel with two fixed lights at the top
             type
             trim
                         None
     4)
          Porch(es)
                         None
     Side: Direction: S
Ь.
     1)
          Bays
                         2 (view obscured by trees)
     2)
          Windows
                         View obscured
             fenestration View obscured
             type
                          View obscured
             trim
                          View obscured
             shutters
                          View obscured
     3)
          Door(s)
                          View obscured
             location
                          View obscured
                          View obscured
             type
                          View obscured
             trim
     4)
          Porch(es)
                          View obscured
     Side: Direction: N
     1)
          Bays.
                         2
          Windows
                         2
     2)
             fenestration Paired 1/1 double-hung sash
                         Paired 1/1 double-hung sash
             type
             trim
                         None
             shutters
                         None
     3)
          Door(s)
                         None
             location
                         N/A
             type
                         N/A
             trim
                         N/A
     4)
          Porch(es)
                         None
d.
    Rear: Direction: W
     1)
          Bays
                         Not visible
          Windows
     2)
                         Not visible
             fenestration Not visible
             type
                         Not visible
             trim
                         Not visible
             shutters
                         Not visible
     3)
          Door(s)
                         Not visible
             location
                         Not visible
```

9. INTERIOR: Not accessible

4)

type

trim

Porch(es)

10. LANDSCAPING: Pine tree border and maintained lawn

Not visible

Not visible

Not visible

11. OTHER COMMENTS: Construction date provided by the owner; plot contains 4.57 ac of land

## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-14133

1.	ADDRESS/LOCATION: 1166 Church Road
2.	FUNCTION(S): historic Barn current Storage
3.	YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Unknown
4.	STYLE/FLOOR PLAN: Side gable with cross gable addition and front and shed roof addition at rear
5.	INTEGRITY: original site 🖂 moved 🗍
	if moved, from where original location's CRS # year
	Hist major alterations and additions with years (if known) a. b.
6.	CURRENT CONDITION: excellent ⊠ good ☐ fair ☐ poor ☐
7.	DESCRIPTION:
	a. Structural system Concrete block
	b. Number of stories 1 1/2
	c. Wall coverings Concrete block
	d. Foundation Not visible
	e. Roof structural system Side gable (main block), cross gable (front), and shed (rear) coverings Metal (current and newly placed) openings None
8.	DESCRIPTION OF ELEVATIONS:
	<ul> <li>a. Facade: direction: E</li> <li>1) bays: 4</li> <li>2) windows: Not visible</li> </ul>
	3) door(s): Not visible
	4) other: N/A

			CRS#	N-14
b.	Sid	de: direction: N		
	1)	bays: 2		
	2)	windows: 6/6 double-hung sash with plywood over lower light; 1/1 vinyl	l replace	ment
	3)	door(s): None		
	4}	other: N/A		
c.	Sid	de: direction: S		
	1)	bays: Not visible		
	2)	windows: Not visible		
	3)	door(s): Not visible		
	4)	other: Not visible		
d.	Rea	ar: direction: W		
-	1)	bays: Not visible		
	2)	windows: Not visible		
	3)	door(s): Not visible		
	4)	other: N/A		
1 <b>2</b> F	KIOR	R (if accessible):		
Flo	or p	olan Not accessible		

- a)
- b) Partition/walls Not accessible
- c) Finishes Not accessible
- d) Furnishings/machinery Not accessible



## **CULTURAL RESOURCE SURVEY** MAP FORM


N-14133 CRS#

1.	ADDRESS/LOCATION:	166 Church Road	 
2.	NOT FOR PUBLICATION	reason:	 
_	LOCATIONALIS		


**LOCATION MAP:** 

Indicate position of resource in relation to geographical landmarks such as streams and crossroads. (attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN



## **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

## PHOTOGRAPHIC INVENTORY

CRS # <u>N-</u> 14 <u>133</u>	Date <u>9/1/2003</u>	_ Photo Roll#	C-4535	Surveyor	Gerald Kuncio	_	
Description 11-Facade and south side, facing NW; 12-Façade, facing W; 13-Barn, facing SW							
Negative location (if other than SHPO)							
Attach contact print(s):							







doc # 20-06-01-85-12

**CRS-13** 

					_
					_
					_
					_
					-
					-
					_
					_
					_
					_
					_
					-
					_
					_
					_
					_
					-
		_	 	_	

## CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-14134
SPO Map	06.07.32
Hundred	New Castle
Quad	St. Georges
Other	10-048-00014

1,	HISTORIC NAME/FUNCTION:	Dwelling, 1200 Church	Road		
2.	ADDRESS/LOCATION: 1200 C	hurch Road (West Side	1)		
3.	TOWN/NEAREST TOWN: Bear	_		v	ricinity? 🛛
4.	MAIN TYPE OF RESOURCE:	building ⊠ landscape □	structure [	site 📋	object 🗌
5.	MAIN FUNCTION OF PROPERTY	: Dwelling			
6.	PROJECT TITLE/ REASON FOR S Church Road (Wynnefield to S.R.		: —		
7. A	DDITIONAL FORMS USED:				
	#: Form:  1 CRS 2 Main Building Form:  1 CRS 3 Secondary Building:  0 CRS 4 Archaeological Site:  0 CRS 5 Structure (Building:  0 CRS 6 Structure (Land Fee:  0 CRS 7 Object Form:  0 CRS 8 Landscape Element	Dwelling Form Garage Form Like) Form ature) Form	erty types:		
	1 CRS 9 Map Form	N/A			
8. S	0 CRS 14 Potential District F	-c <u>rm</u>			
S	urveyor name:	Gerald M. Kuncio			
P	rincipal Investigator name:	Ger <u>ald M. Kuncio</u>			
P	rincipal Investigator signature:				
c	Prganization:	Skelly and Loy, Inc.		Date:	9/2/2003

Dwelling constructed d	uring the post-World War II e	era	
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check a	ll appropriate boxes; refer to state ma	nagement
a) Time period(s)	Pre-European Cor Paleo-Indian Archaic Woodland I Woodland II	ntact	
	1600-1750 L Contact Period 1630-1730 ± Exploration and 1730-1770 ± Intensified and 1770-1830 ± Early Industrial 1830-1880 ± Industrialization 1880-1940 ± Urbanization and 1940-1960 ± Suburbanization	d Frontier Settlement Durable Occupation Ization n and Early Urbanization	
b) Geographical zone	Coastal	nsula nsula/Cypress Swamp of Wilmington)	
c) Historic period them	e(s)		
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	Transportation and Communicati  Settlement Patterns and Demogra Architecture, Engineering and De Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and E	aphic Changes corative Arts
	USE BLACK	INK ONLY	crs-1

CRS# N-14134

9. OTHER NOTES OR OBSERVATIONS:



## CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	N-14134	

1.	ADDRESS/LOCATION: 1200 Church Road
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling
3.	YEAR BUILT: 1958 CIRCA?: ARCHITECT/BUILDER: Unknown
4.	STYLE OR FLOOR PLAN: L-shaped vernacular w/ hyphen and attached garage
5.	INTEGRITY: original site ⊠ moved □
	if moved, from where other location's CRS # year
	list major alterations and additions with years (if known)  a. b.
6.	CURRENT CONDITION: excellent  good  fair poor
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	a. Overall shape: L-shaped with hyphen and Stories: 1 attached garage Additions: Hyphen between garage and house
	b Structural system (if known): Balloon frame
	c. Foundation: materials: Not visible basement ☐
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding and face brick
	e. Roof: shape: Cross gable materials: Asphalt shingle cornice: Gable returns dormers: None chimney: location(s): 2 - Brick exterior; south side of main block and south end of hyphen
8.	DESCRIPTION OF ELEVATIONS:
	<ul> <li>a. Facade: Direction: E</li> <li>1) Bays 3; south end has cross gable roof and extends, creating L-shape</li> <li>2) Windows 2         fenestration Symmetrical         type Plate glass picture window w/ vertical dividers; paired 1/1 vinyl sash         trim Brick sills         shutters None</li> </ul>

```
Facade (cont'd)
           Door(s)
             location
                          Centered
             type
                          Fixed light and 3 raised panels
             trim
     4)
           Porch(es)
                          1 Bay , 1 story under the eaves of the cross gable with a single bedpost
          column and a poured concrete floor
     Side: Direction: S
b.
     1)
          Bays
     2)
          Windows
                          None
             fenestration N/A
                          N/A
             type
             trim
                          N/A
             shutters
                          N/A
     3)
          Door(s)
                          One, leading to the hypen and garage
             location
                          Not visible
             type
                          Not visible
                          Not visible
             trim
     4)
          Porch(es)
                          1 Bay, 1 story side gable hyphen connects the house and garage; hyphen
          door: 15 light wood; windows: 1/1 vinyl sash
     Side: Direction: N
C.
     1)
          Bavs
                          3 plus 1 in the cross gable extension
     2)
          Windows
             fenestration Regular
             type
                          1/1 vinyl sash
             trim
                         None
             shutters
                         None
     3)
                         None
          Door(s)
             location
                         N/A
                         N/A
             type
             trim
                         N/A
     4)
          Porch(es)
                         None
ď.
     Rear: Direction: W
     1)
                         Not visible
          Bays
    2)
          Windows
                         Not visible
             fenestration Not visible
             type
                         Not visible
             trim
                         Not visible
             shutters
                         Not visible
    3)
                         Not visible
          Door(s)
             location
                         Not visible
             type
                         Not visible
             trim
                         Not visible
    4)
          Porch(es)
                         Not visible
```

- 9. INTERIOR: Not accessible
- 10. LANDSCAPING: Pine tree border and maintained lawn; long, half-circle driveway
- 11. OTHER COMMENTS: Construction date from tax assessment records



## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-14134

1.	ADDRESS/LOCATION: 1200 Church Road	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: Single bay gable end with extension to the south side	
5.	INTEGRITY: original site 🖾 moved 🗌	
	if m <u>oved, from</u> whe <u>re</u> <u>original location</u> 's CRS#	year
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent ⊠ good ☐ fair ☐	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vinyl slding	
	d. Foundation Not visible	
	e. Roof structural system Gable end with overhanging eaves coverings Asphalt shingles openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul><li>a. Facade: direction: E</li><li>1) bays: 1</li><li>2) windows: N/A</li></ul>	
	3) door(s): Roll-up garage door w/ 5 fixed lights	
	4) other: N/A	

CRS # N-14134

b.	Side:	direction:	Ν
	<b>G100.</b>		

1) bays: Not visible

2) windows: Not visible

3) door(s): Not visible

4) other: Connected by hyphen to the house

c. Side: direction: S

1) bays: Not visible

2) windows: Not visible

3) door(s): Not visible

4) other: Not visible

d. Rear: direction: W

1) bays: Not visible

2) windows: Not visible

3) door(s): Not visible

4) other: N/A

### 9. INTERIOR (if accessible):

a) Floor plan

Not accessible

b) Partition/walls

Not accessible

c) Finishes

Not accessible

d) Furnishings/machinery


Not accessible

## **CULTURAL RESOURCE SURVEY MAP FORM**

CRS # N-14	134
------------	-----

	Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
3.	LOCATION MAP:
2.	NOT FOR PUBLICATION
1.	ADDRESS/LOCATION: 1200 Church Hoad

(attach section of USGS quad map with location marked or draw location map )



INDICATE NORTH ON PLAN NOT TO SCALE CHIMNEY WORNIW -HOUSE HYPHEN W H000R Ţ DRIVEWAY DRIVEWAY CHURCH ROAD

N-14134

## **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

### PHOTOGRAPHIC INVENTORY

CRS#	N-14134	Date <u>9/1/2003</u>	_ Photo Roll #	C-4535	Surveyor	Gerald Kuncio
Descrip	tion 14-Portion o	f facade and north	side, facing W ;	15-Façade	е, һурһел, а	ind garage, facing
Negativ	e location (if othe	r than SHPO) _				<del></del>
Attach o	contact print(s):					
_						

doc#20-06-01-05-12

**CRS-13** 

		-
		-~
		-
		-
		-
		-
		_
		~
		_
		_
		_
		_
		_

## CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-14137
SPO Map	06.07.32
Hundred	New Castle
Quad	St. Georges
Other	10-048-00019

					<u> </u>
1.	HISTO	ORIC NAME/FUNCTION:	Owelling, 1307 Churc	ch Road	
2.	ADDR	RESS/LOCATION: 1307 C	nurch Road (East Sid	de)	
3.	TOWN	N/NEAREST TOWN: Bear			vicinity? 🛛
4.	MAIN	TYPE OF RESOURCE:	building ⊠ landscape □	structure  district	site 🗌 object 🗌
5.	MAIN	FUNCTION OF PROPERTY	: Dwelling		
6.		ECT TITLE/ REASON FOR S th Road (Wynnefield to S.R.		le):	
7. /	ADDITIO	ONAL FORMS USED:			
	#:	Form:	List pr	operty types:	
	1 CRS 2 Main Building Form Dwelling				
	2	CRS 3 Secondary Building		e, Shed	
	0	CRS 4 Archaeological Site	Form	•	
	0	CRS 5 Structure (Building	Like) Form		
	O	CRS 6 Structure (Land Fea	ture) Form		
	0	CRS 7 Object Form			
	0	CRS 8 Landscape Element			
	1	CRS 9 Map Form	N/A		
	0	CRS 14 Potential District F	orm		
8. \$	SURVE	YOR INFORMATION:			
	Surveyo	or name:	Gerald M. Kuncio		
	Principa	al Investigator name:	Gerald M. Kuncio		
	Principa	al Investigator signature:			
	Organiz	Date: 9/2/2003			

Dwelling constructed during the post-World War II era				
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check all appropriate boxes; refer to state management			
a) Time period(s)	☐ Pre-European Contact ☐ Paleo-Indian			
	Archaic Woodland I			
	Woodland II			
	1600-1750± Contact Period (Native American) 1630-1730+ Exploration and Frontier Settlement			
	1730-1770± Intensified and Durable Occupation			
Ä	1770-1830± Early Industrialization 1830-1880± Industrialization and Early Urbanization			
	1880-1940± Urbanization and Early Suburbanization 1940-1960± Suburbanization and Early Ex-urbanization			
b) Geographical zone	Piedmont			
	<ul><li>☐ Coastal</li><li>☐ Urban (City of Wilmington)</li></ul>			
c) Historic period them	_ , , , , , , , , , , , , , , , , , , ,			
	Agriculture			
Ä	Forestry Settlement Patterns and Demographic Changes			
	Trapping/Hunting Architecture, Engineering and Decorative Arts  Mining/Quarrying Government			
	Fishing/Oystering Religion  Manufacturing Education			
	Retailing/Wholesaling Community Organizations Finance Occupational Organizations			
ä	Professional Services Major Families, Individuals and Events			

**USE BLACK INK ONLY** 

CRS# N-14137

CRS-1

9. OTHER NOTES OR OBSERVATIONS:



doc# 20-06-01-05-02

## CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

crs# N-14137

CRS-2

	<del></del>	
1.	ADDRESS/LOCATION: 1307 Church Road	
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling	
3.	YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: Unknown	
4.	\$TYLE OR FLOOR PLAN: Post-World War II vernacular with Ranch elements	
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where other location's CRS#	<u>year</u>
	<u>list major alterations and additions with years (if known)</u> a. All construction south of the front door does not appear to be original	<u>year</u>
	b. Vertical board siding, enclosed porch with louvered windows	
6.	CURRENT CONDITION: excellent ⊠ good □ fair □ poor □	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave blanks.)	no
	<ul> <li>a. Overall shape: Historic: Rectangular; Current: Stories: 1 1/2</li> <li>L-shaped</li> <li>Additions: All construction south of the front door</li> </ul>	
	b Structural system (if known): Balloon frame	
	c. Foundation: materials: Brick (visible material) basement: full ☐ partial ⊠ not visible ☐ no basement ☐	
	d. Exterior walls (original if visible& any subsequent coverings): Vertical board (not historic)	
	e. Roof: shape: Side gable materials: Asphalt shingle cornice: Open dormers: None chimney: location(s): Brick interior; centered at the ridge line of the south half	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: Direction: W</li> <li>1) Bays 3 original; now 6</li> <li>2) Windows 5         fenestration Irregular         type Casement, 9-light jalousie; projecting bay window with 4 divisions, each eight lights; 6-light fixed sash         trim None         shutters Fixed, decorative vinyl on 6-light fixed sash</li> </ul>	ı with

USE BLACK INK ONLY

```
Facade (cont'd)
          Door(s)
             location
                          South end of original block
             type
                          Wood with raised panel and fixed light
                          None
             trim
     4)
          Porch(es)
                          Enclosed, 2-bay porch with jalousie windows
     Side: Direction: N
                          2
     1)
          Bays
     2)
          Windows
                          1
             fenestration Centered
                          1/1 metal sash
             type
             trim
                         None
             shutters
                         None
     31
          Door(s)
                         None
             location
                         N/A
                         N/A
             type
             trim
                         N/A
     4)
          Porch(es)
                         None
     Side: Direction: S
          Bays
     1)
     2)
          Windows
                         Bank covers nearly the entire wall
             fenestration Bank covers nearly the entire walf
             type
                         Not visible
             trim
                         Not visible
                         None
             shutters
     3)
                         None
          Door(s)
                         N/A
             location
                         N/A
             type
                         N/A
             trim
     4)
          Porch(es)
                         None
d.
    Rear: Direction: E
          Bays
     1)
                         Not visible
     2)
          Windows
                         Not visible
             fenestration Not visible
             type
                         Not visible
             trim
                         Not visible
             shutters
                         Not visible
     3)
                         Not visible
          Door(s)
             location
                         Not visible
```

9. INTERIOR: Not accessible

4)

type

trim

Porch(es)

- 10. LANDSCAPING: Set back from road on landscaped lawn with plantings; surrounding setting is wooded
- 11. OTHER COMMENTS: Construction date from tax assessment records

Not visible

Not visible

Not visible



## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-14137

1.	ADDRESS/LOCATION: 1307 Church Road
2.	FUNCTION(S): historic Garage current Garage
3.	YEAR BUILT: 1955 CIRCA?:   ARCHITECT/BUILDER: Unknown
4.	STYLE/FLOOR PLAN: _2-bay gable end
5.	INTEGRITY: original site 🖂 moved 🗌
	If moved, from where original location's CRS # year
	list major alterations and additions with years (if known)  a. b.
6.	CURRENT CONDITION: excellent  good  fair poor
7.	DESCRIPTION:
	a. Structural system Frame
	b. Number of stories 1
	c. Wall coverings Vinyl siding
	d. Foundation Poured concrete
	e. Roof structural system Gable end coverings Asphalt shingles openings Brick exterior chimney on the east side
8.	DESCRIPTION OF ELEVATIONS:
	<ul><li>a. Facade: direction: S</li><li>1) bays: 2</li><li>2) windows: None</li></ul>
	3) door(s): 2 Roll-up garage doors w/ 4 fixed sash each
	4) other: N/A

CRS#	N-14137
URO#	14-14-13/

b.	Sid: 1) 2)
	3)
	4)
¢.	Side 1) 2)
	3)
	4)
ď.	Rea 1) 2)
	3)
	4)

e: direction: W

bays: 3

windows: One 2/2 fixed sash, centered

door(s): None

other: N/A

e: direction: E

bays: 2

windows: Not visible

door(s): Not visible

other: Not visible

r: direction: N

bays: 2

windows: None

door(s): None

other: Flat roof lean-to at rear

### 9. INTERIOR (if accessible):

a) Floor plan

Not accessible

b) Partition/walls

Not accessible

c) Finishes

Not accessible

d) Furnishings/machinery

Not accessible



## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	N-14137	

1.	ADDRESS/LOCATION: 1307 Church Road	
2.	FUNCTION(S): historic Shed current Shed	
3.	YEAR BUILT:1990	
4.	STYLE/FLOOR PLAN: 1-bay with gambrel roof	
5.	INTEGRITY: original site	<u>year</u>
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent \( \times \) good \( \times \) fair \( \times \)	poor [
7.	DESCRIPTION:	
	a. Structural system Formed metal	
	b. Number of stories 1	
	c. Wall coverings Aluminum	
	d. Foundation Not Visible	
	e. Roof structural system Gambrel end coverings Asphalt shingles openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul><li>a. Facade: direction: S</li><li>1) bays: 1</li><li>2) windows: None</li></ul>	
	3) door(s): Double aluminum doors with 3 fixed vertical sash	
	4) other: N/A	

b.	1)	e: direction: W bays: Not visible windows: Not visible
	3)	door(s): Not visible

4) other; N/A

c. Side: direction: E1) bays: Not visible2) windows: Not visible

3) door(s): Not visible

4) other: Not visible

d. Rear: direction: N1) bays: Not visible2) windows: Not visible

3) door(s): Not visible

4) other: Not visible

### 9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



## **CULTURAL RESOURCE SURVEY** MAP FORM

CRS#	N-14137	


1.	ADDRESS/LOCATION:	1307 Church Road	 

NOT FOR PUBLICATION reason:

**LOCATION MAP:** 

Indicate position of resource in relation to geographical landmarks such as streams and crossroads. (attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



# INDICATE NORTH ON PLAN NOT TO SCALE - CHIMNEY HOUSE $\vdash$ W T w H TDOOR T T SHED ⊢ □ T ... CHIMNEY 一口 $\vdash$ $\upsilon$ GARAGE CRIVEWAY CHURCH ROAD N 14137

## **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

## PHOTOGRAPHIC INVENTORY

CRS#	<u>N-14</u> 137	Date	9/2 <u>00</u> 3	_ Photo Roll #	_C-45 <u>35</u>	Surveyor	Gerald Kuncio
garage	otion 20-Facade , facing SE; 22 acing NE; 25 - E	South end	d, facing NE	E; 23 - Garage a	_		nship of house and 4 - Garage and 
Negativ	e location (if otl	her than S	HPO)				
Attach	contact print(s):					22	2
			27		24		42
daa # 30 0	SE 04 DE 13						cas-13

		-
		-
		_
		٠.
		_
		_
		_
		~
		_
		_
		_
		_
		_
		_
		~
		_

## CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-14139
SPO Map	06.07.32
Hundred	New Castle
Quad	St. Georges
Other	10-048-00015

1,	HISTORIC NAME/FUNCTION:	welling, 1444 Church Road				
2.	ADDRESS/LOCATION: 1444 Church Road (West Side)					
3.	TOWN/NEAREST TOWN: Bear			vicinity? 🖂		
4.	MAIN TYPE OF RESOURCE:	building 🖾 structure 🗌 landscape 🗌 district 📑	site 🗌	object 🗌		
5.	MAIN FUNCTION OF PROPERTY	Dwelling				
6.	PROJECT TITLE/ REASON FOR S Church Road (Wynnefield to S.R.					
7. /	ADDITIONAL FORMS USED:					
	#: Form:	List property types:				
	1 CRS 2 Main Building Form	Dwelling				
	1 CRS 3 Secondary Building					
	0 CRS 4 Archaeological Site					
	0 CRS 5 Structure (Building-					
	0 CRS 6 Structure (Land Fea	ture) Form				
	0 CR\$ 7 Object Form					
	0 CRS 8 Landscape Element					
	1 CRS 9 Map Form	N/A				
	0 CRS 14 Potential District F	orm				
8. \$	SURVEYOR INFORMATION:					
!	Surveyor name:	Gerald M. Kuncio				
١	Principal Investigator name: Gerald M. Kuncio					
ı	Principal Investigator signature:					
(	Örganization:	Skelly and Loy, Inc.	Date:	9/2/2003		

10. STATE HISTORIC CON <sup>-</sup> plan(s)):		ropriate boxes; refer to state manage	ement
a) Time period(s)	☐ Pre-European Contact ☐ Paleo-Indian ☐ Archaic ☐ Woodland I ☐ Woodland II		
	1600-1750+ Contact Period (Nation 1630-1730+ Exploration and From 1730-1770+ Intensified and Dural 1770-1830+ Early Industrialization 1830-1880+ Industrialization and 1880-1940+ Urbanization and Early 1940-1960+ Suburbanization and	itier Settlement ble Occupation n Early Urbanization ly Suburbanization	
b) Geographical zone	☐ Piedmont ☐ Upper Peninsula ☐ Lower Peninsula ☐ Coastal ☐ Urban (City of W		
c) Historic period them	e(s)		
	Forestry S Trapping/Hunting A Mining/Quarrying G Fishing/Oystering R Manufacturing G Retailing/Wholesaling G Finance G	ransportation and Communication ettlement Patterns and Demographic rchitecture, Engineering and Decoratovernment eligion ducation ommunity Organizations lajor Families, Individuals and Event	tive Arts
	USE BLACK INK O	NLY	crs-1

USE BLACK INK ONLY

9. OTHER NOTES OR OBSERVATIONS:

CRS# N-14139 \_



doc# 20-06-01-05-02

## CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

rs# N-14139
-------------

crs-2

1.	ADDRESS/LOCATION: 1444 Church Road	
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling	
3.	YEAR BUILT: 1933 CIRCA?: ARCHITECT/BUILDER: Unknown	
4.	STYLE OR FLOOR PLAN: 3-bay side gable vernacular	_
5.	INTEGRITY: original site	уеаг
	list major alterations and additions with years (if known) a. b.	уеаг
6.	CURRENT CONDITION: excellent  good  fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leaviblanks.)	e no
	a. Overall shape: T-shaped Stories: 1 Additions:	
	b Structural system (if known): Balloon frame	
	c. Foundation: materials: Concrete block basement: full ⊠ partial □ not visible □ no basement □	
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding	
	e. Roof: shape: Side gable materials: Asphalt shingle cornice: Open dormers: None chimney: location(s): Brick interior; centered at the ridge line	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: Direction: E</li> <li>1) Bays 4</li> <li>2) Windows 7 fenestration tregular type House: 1/1 double-hung wood sash grouped singly and in pairs; encliporch: four 1/1 vinyl sash trim Plain metal frames shutters None</li> </ul>	osed

USE BLACK INK ONLY

```
CRS#
                                                                                   N-14139
     Facade (cont'd)
          Door(s)
                          Centered (inside enclosed porch)
             location
                          Wood replacement door with 9 lights (3/3/3)
             type
             trim
                          None
     4)
          Porch(es)
                          2-bay X 1-bay, single story with shed roof and vinyl siding
     Side: Direction: N
b.
          Bays
                          2 plus 1-bay rear addition
     1)
     2)
          Windows
                          3
             fenestration Irregular
                          1/1 wood sash and 1/1 vinyl sash in rear addition
             type
             trim
                         Plain metal frames
                         None
             shutters
     3)
          Door(s)
                          On rear addition
                         North end
             location
                         Not visible
             type
             trim
                         None
     4)
          Porch(es)
                         Wood deck and stairs with lattice skirt
     Side: Direction: S
C.
                         2
          Bays
     1)
     2)
          Windows
                         2
             fenestration Regular
             type
                          1/1 wood sash
                          Plain metal frames
             trim
                         None
             shutters
                         None
     3)
          Door(s)
                         N/A
             location
                         N/A
             type
                         N/A
             trim
                         None
     4)
          Porch(es)
d.
     Rear: Direction: W
          Bays
                         Not visible
     1)
     2)
          Windows
                         Not visible
             fenestration Not visible
             type
                         Not visible
                         Not visible
             trim
             shutters
                         Not visible
     3)
                         Not visible
          Door(s)
             location
                         Not visible
                         Not visible
             type
             trim
                          Not visible
```

9. INTERIOR: Not accessible

Porch(es)

4)

10. LANDSCAPING: Set near the road on a lawn with minimal landscaping

Not visible

11. OTHER COMMENTS: Construction date from tax assessment records

# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-14139

1.	ADDRESS/LOCATION: 1444 Church Road	
2.	FUNCTION(S): historic Shed current Shed	
3.	YEAR BUILT: 1955 CIRCA?: X ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: Gable end	
5.	INTEGRITY: original site 🖂 moved 🗌	
	if moved, from where original location's CRS#	<u>year</u>
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent 🗵 good 🗌 fair 📋	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vinyl siding	
	d. Foundation Concrete block piers	
	e. Roof structural system Frame coverings Asphalt shingles openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul><li>a. Facade: direction: N</li><li>1) bays: 1</li><li>2) windows: None</li></ul>	
	3) door(s): 1 solid panel	
	4) other: N/A	

				CRS# N	l <u>-1</u> 4139
	b.	Sid	ide: direction: E		<u> </u>
		1)	bays: 1		
		2)	windows: None		
		3}	door(s): 1 - solid wooddoes not appear to be original		
		4)	other: N/A		
	c.	Sid	ide: direction: S		
		1)			
		2)			
		ŕ			
		3)	door(s): None		
		4)	other: N/A		
	d.	Re	ear: direction: W		
	٠	1)	<del></del>		
		2)			
		•			
		3)	door(s): Not visible		
		4)	other: N/A		
9.	INTE	RIOF	PR (if accessible):		
	a) Flo	oor p	plan Not accessible		
	-	-			

b) Partition/walls Not accessible

c) Finishes Not accessible

### d) Furnishings/machinery Not accessible

## CULTURAL RESOURCE SURVEY MAP FORM

CRS# N-14139


1.	ADDRESS/LOCATION:	1444 Church Road	 


3. LOCATION MAP:

 $Indicate\ position\ of\ resource\ in\ relation\ to\ geographical\ landmarks\ such\ as\ streams\ and\ crossroads.$ 

(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH





### **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

### PHOTOGRAPHIC INVENTORY

CRS#	N-14139	Date	9/2003	Photo Roll#	C-4536	Surveyor	Gerald Kuncio
Descript facing V		nd north	ı side, facing	j SW; 7 - Facad	de and sou	th side, faci	ng NW; 8 - Shed,
_ Negative	e location (if other	r than S	6HPO)				
_ Attach c	ontact print(s):						
						-1-2-7	-
_			-				<i>r</i>
-		M	THE COLUMN			基基里	

doc # 20-06-01-05-12 CRS-13

		-
		-
		_
		-
		_
		-
		_
		-
		_
		_
		_
		-
		-
		_
		-
		_
		_
		_
. <u>-</u>		

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-14140
SPO Map	06.07.32
Hundred	New Castle
Quad	St. Georges
Other	10-048-00016

			Other	10-048-00010
1.	HISTORIC NAME/FUNCTION:	Dwelling, South of 1444 Church Road		
2.	ADDRESS/LOCATION: South	Of 1444 Church Road (West Side)		
3.	TOWN/NEAREST TOWN: Bear			vicinity? 🛛
4.	MAIN TYPE OF RESOURCE:	building ⊠ structure ☐ landscape ☐ district ☐	site	object
5.	MAIN FUNCTION OF PROPERTY	: Dwelling		
6.	PROJECT TITLE/ REASON FOR S Church Road (Wynnefield to S.R.			_
7.	ADDITIONAL FORMS USED:			
	#: Form:	List property types:		
	1 CRS 2 Main Building Form		_	
	0 CRS 3 Secondary Building			
	0 CRS 4 Archaeological Site			
	0 CRS 5 Structure (Building			
	0 CRS 6 Structure (Land Fea	ature) Form		
	0 CRS 7 Object Form			
	0 CRS 8 Landscape Elemen	ts Form		
	1 CRS 9 Map Form	N/A		
	0 CRS 14 Potential District F	orm		
8.	SURVEYOR INFORMATION:			
	Surveyor name:	Gerald M. Kuncio		_
	Principal Investigator name:			
	Principal Investigator signature:			
	Organization:	Skelly and Loy, Inc.	0	Pate: 9/2/2003

10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (chec	ck all appropriate boxes; ref	er to state management
a) Time period(s)	Pre-European Paleo-Indian Archaic Woodland I Woodland II	Contact	
	1730-1770± Intensified a 1770-1830± Early Indust 1830-1880± Industrializa 1880-1940± Urbanizatio	and Frontier Settlement and Durable Occupation	1
b) Geographical zone	Lower F	Peninsula Peninsula/Cypress Swamp	
c) Historic period them	e(s)		
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services		and Demographic Changes eering and Decorative Arts eations dizations
	USE BLA	CK INK ONLY	crs- <b>1</b>

CRS# N-14140

9. OTHER NOTES OR OBSERVATIONS:

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-14140

1.	ADDRESS/LOCATION: South Of 1444 Church Road	
2.	FUNCTION(S): historic Single family dwelling current Vacant	_
3.	YEAR BUILT: 1943 CIRCA?: ARCHITECT/BUILDER: Unknown	
4.	STYLE OR FLOOR PLAN: L-shaped vernacular	
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. b.	year
ŝ.	CURRENT CONDITION: excellent  good  fair  poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave in blanks.)	10
	a. Overall shape: L-shaped Stories: 1 Additions: None	
	b Structural system (if known): Balloon frame	
	c. Foundation: materials: Concrete block piers basement: full ☐ partial ☐ not visible ☐ no basement ⊠	
	d. Exterior walls (original if visible& any subsequent coverings): Asphalt insulbrick and tarpaper	
	e. Roof: shape: Side gable with gable end over ell materials: Asphalt shingle cornice: Open with exposed rafter tails dormers: None chimney: location(s): Brick interior; at the ridge line near the front of the ell	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: Direction: E 1) Bays 4 2) Windows 3 fenestrationRegular type 1/1 double-hung wood sash trim Plain wood frames shutters None	

```
Facade (cont'd)
     3)
          Door(s)
                         Second bay from north end
             location
             type
                         Wood raised panel with 3 lights
                         Plain wood frame
             trim
          Porch(es)
     4)
                         1-story, 2-bay with a concrete floor, squared wood posts, and cross gable roof
          with asphalt shingles
b.
     Side: Direction: N
                         2 (including rear ell)
     1)
          Bays
     2)
          Windows
                         4
             fenestration Regular
             type
                         1/1 double-hung wood sash
                         Plain wood frames
             trim
             shutters
                         None
     3)
          Door(s)
                         None
             location
                         N/A
             type
                         N/A
             trim
                         N/A
     4)
          Porch(es)
                         None
     Side: Direction: S
C.
     1)
          Bays
     2)
          Windows
             fenestration Regular
                         1/1 double-hung wood sash
             type
             trim
                         Plain wood frames
             shutters
                         None
     3)
                         None
          Door(s)
                         N/A
             location
                         N/A
             type
                         N/A
             trim
          Porch(es)
     4)
                         None
d.
    Rear: Direction: W
     1)
          Bays
                         3
    2)
          Windows
                         2
             fenestration Regular
                         1 - 1/1 double-hung wood sash; 1 with 2 fixed lights
             type
             trim
                         Plain wood frames
             shutters
                         None
    3)
          Door(s)
                         2nd bay from north end
             location
             type
                         Wood raised panel with 3 lights
             trim
                         Plain wood frame
    4}
          Porch(es)
                         None
```

- 9. INTERIOR: Not accessible
- 10. LANDSCAPING: Set near the road with a small setback
- 11. OTHER COMMENTS: Construction date from tax assessment records



## CULTURAL RESOURCE SURVEY MAP FORM


1.	ADDRESS/LOCATION:	South of 1444 Church Road
2.	NOT FOR PUBLICATION	reason:

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN



### **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

### PHOTOGRAPHIC INVENTORY

_CRS#	N-14140	Date	9/2003	_ Photo Roll #	C-4536	Surveyor	Gerald Kuncio
Description 9 - Facade, south side, and portion of rear ell, facing NW; 10 - Facade, north side, and _rear ell, facing SW							
Negative	e location (if othe	r than S	SHPO) _				
_ Attach c	ontact print(s):						
- -			- 44			A 10	

doc # 20-06-01-05-12

**crs-13** 

		_
		~
		_
		_
		_
		_
		-
		_
		-
		-
		_
		_
		_
		_
		_
		_
		_
		_
		_

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

1. HISTORIC NAME/FUNC	TION: Dwelling, 1458 Church Road						
2. ADDRESS/LOCATION:	·						
3. TOWN/NEAREST TOWN	 N: Bear	vicinity? 🖂					
4. MAIN TYPE OF RESOU	MAIN TYPE OF RESOURCE: building  structure  site						
5. MAIN FUNCTION OF P	ROPERTY: _Dwelling						
	SON FOR SURVEY (if applicable): eld to S.R. 71) Improvements						
7. ADDITIONAL FORMS USE	ED:						
#: Form:	List property types:						
1 CRS 2 Main Build							
1 CRS 3 Secondary							
0 CRS 4 Archaeolo							
	(Building-Like) Form						
	(Land Feature) Form						
0 CRS 7 Object For							
	e Elements Form N/A						
1 CRS 9 Map Form 0 CRS 14 Potential							
SURVEYOR INFORMATION		<del></del> -					
Surveyor name:	Gerald M. Kuncio						
Principal Investigator nan	me: Gerald M. Kuncio						
Principal Investigator sig	nature:						
Organization:	Skelly And Loy, Inc.	Date: 9/2/2003					

Dwelling constructed d	uring the post-World War II era	
io. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check all appropriat	e boxes; refer to state management
a) Time period(s)	Pre-European Contact Paleo-Indian Archaic Woodland I Woodland II	
	1600-1750± Contact Period (Native Ame 1630-1730± Exploration and Frontier Se 1730-1770± Intensified and Durable Occ	ttlement
	1770-1830± Early Industrialization 1830-1880± Industrialization and Early I 1880-1940± Urbanization and Early Sub 1940-1960± Suburbanization and Early	urbanization
b) Geographical zone	☐ Piedmont ☐ Upper Peninsula	
	<ul><li>Lower Peninsula/Cypre</li><li>Coastal</li><li>Urban (City of Wilmingt</li></ul>	-
c) Historic period them	e(s)	
	Forestry	l e e e e e e e e e e e e e e e e e e e
	Retailing/Wholesaling	nity Organizations tional Organizations amilies, Individuals and Events
	USE BLACK INK ONLY	crs-1

CRS# N-14141

9. OTHER NOTES OR OBSERVATIONS:



# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

	-d	
1.	ADDRESS/LOCATION: 1458 Church Road	
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling	
3.	YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Unknown	
1.	STYLE OR FLOOR PLAN: 20th century vernacular	
5.	INTEGRITY: original site 🗵 moved 🔲	
	if moved, from where other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a	year —
<b>3</b> .	CURRENT CONDITION: excellent  good  fair  poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave blanks.)	e no
	a. Overall shape: Square Stories: 1 Additions: None	
	b Structural system (if known): Balloon frame	
	c. Foundation: materials: Parged - either poured concrete or concrete block basement: full 🗵 partial 🔲 not visible 🗌 no basement 🗍	
	d. Exterior walls (original if visible& any subsequent coverings): Asphalt shingle	
	e. Roof: shape: Side and front gable materials: Asphalt shingle cornice: Open dormers: None chimney: location(s): Brick interior; centered rear of roof	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: Direction: E  1) Bays 3  2) Windows 2 fenestratioπRegular type 1/1 double-hung wood sash trim Plain wood frames	

shutters

None

```
Facade (cont'd)
          Door(s)
             location
                         Centered
                         Wood paneled with single fixed light
             type
                         Plain wood surrounds
             trim
    4)
                         Wood stoop
          Porch(es)
    Side: Direction: S
b.
                         3
    1)
          Bavs
                         2
    2)
          Windows
             fenestration Regular
                         1/1 double-hung wood sash with vinyl storm windows
             trim
                         Plain wood surrounds
             shutters
                         None
    3)
          Door(s)
                         None
             location
                         N/A
                         N/A
             type
                         N/A
             trim
    4)
          Parch(es)
                         None
    Side: Direction: N
          Bays
                         3
    1}
    2)
          Windows
                         2
             fenestration Regular
                         1/1 double-hung wood sash with vinyl storm windows
             trim
                         Plain wood surrounds
                         None
             shutters
    3)
          Door(s)
                         None
             location
                         N/A
                         N/A
             type
                         N/A
             trim
    4)
          Porch(es)
                         None
    Rear: Direction: E
                         Not visible
    1)
          Bays
    2)
          Windows
                         Not visible
             fenestration Not visible
             type
                         Not visible
             trim
                         Not visible
                         Not visible
             shutters
    3)
          Door(s)
                         Not visible
                         Not visible
             location
                         Not visible
             type
                         Not visible
             trim
    4)
          Porch(es)
                         Not visible
```

- 9. INTERIOR: Not accessible
- LANDSCAPING: Small set back from the road and minimal landscaping
- 11. OTHER COMMENTS: Construction date estimated from tax assessment and deed records



# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-14141

1.	ADDRESS/LOCATION: 1458 Church Road	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1955 CIRCA?: X ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: 1-story, 1-bay gable end	
5.	INTEGRITY: original site 🗵 moved 🗌	
	if moved, from where original location's CRS #	y <u>ear</u>
	list major alterations and additions with years (if known) a. b.	Year
6.	CURRENT CONDITION: excellent ☐ good ☐ fair ⊠	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Asphalt siding	
	d. Foundation Poured concrete	
	e. Roof structural system Gable end coverings Asphalt shingles openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: E 1) bays: 1 2) windows: None	
	3) door(s): 2 vertical board wood doors	

4) other: N/A

CRS#	N-14141	
------	---------	--

b. Side: direction: N

1) bays: 2

2) windows: 1 with six lights - either fixed or top hinged

3) door(s): None

4) other: N/A

c. Side: direction: S

1) bays: 2

2) windows: 1 with six lights - either fixed or top hinged

3) door(s): None

4) other: None

d. Rear: direction: W

1) bays: 1

2) windows: Not visible

door(s): Not visible

4) other: N/A

INTERIOR (if accessible):

a) Floor plan

Not accessible

b) Partition/walls Not accessible

c) Finishes

Not accessible

d) Furnishings/machinery Not accessible

# CULTURAL RESOURCE SURVEY MAP FORM

CRS#	N-14141	
CPG#	14-1-47-41	


1.	ADDRESS/LOCATION:	1458 Church Road	
2.	NOT FOR PUBLICATION	reason:	

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN

NOT TO SCALE



N-14141

### **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

### PHOTOGRAPHIC INVENTORY

CRS#	N-14141	Date	_9/2003	Photo Roll#	C-4 <u>536</u>	Surveyor	Gerald Kuncio
Description 11 - Facade and south side, facing NW; 12 - Garage, facing W							
Negative location (if other than SHPO)							
Attach contact print(s):							





dac # 20-06-01-05-12

**crs-13** 

	_
	_
	-
	-
	-+
	_
	_
	-
	-
	-
	-

### **CULTURAL RESOURCE SURVEY** PROPERTY IDENTIFICATION FORM

CRS # SPO Map Hundred Quad Other	N-14142 06.07.32 New Castl St. George 10-048-000	25
 site [	vicinity?	  ⊠ t _
 		 -
 		<u> </u>

				Other	10-048-00024
1.	HISTORIC NAME/FUNCTION:	Dwelling, 1453 Churcl	Road		
2.	ADDRESS/LOCATION: 1453 C	hurch Road (West Sid	le)		
3.	TOWN/NEAREST TOWN: Bear				vicinity? 🛚
4.	MAIN TYPE OF RESOURCE:	building ⊠ landscape ∏	structure [] district []	site 📋	object 🗌
<b>5</b> .	MAIN FUNCTION OF PROPERTY	: Dwelling			
6.	PROJECT TITLE/ REASON FOR S Church Road (Wynnefield to S.R.		): 		
7. /	ADDITIONAL FORMS USED:				
	#: Form:	List pro	perty types:		
	1 CRS 2 Main Building Form		<u> </u>		
	1 CRS 3 Secondary Building				
	0 CRS 4 Archaeological Site				
	0 CRS 5 Structure (Building				
	0 CRS 6 Structure (Land Fea	iture) Form	_		
	0 CRS 7 Object Form 0 CRS 8 Landscape Element				
	1 CRS 9 Map Form	N/A			
	0 CRS 14 Potential District F				
B. :	SURVEYOR INFORMATION:				
	Surveyor name:	Gerald M. Kuncio			
	Principal Investigator name:	Gerald M. Kuncio		<del>_</del>	
	Principal Investigator signature:				
	Organization:	Skelly an <u>d Loy, I</u> nc.		Date	9/2/2003

Dwelling constructed de	uring the post-World Wa	r II <del>e</del> ra	
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (chec	k all appropriate boxes; refer	to state management
a) Time period(s)	☐ Pre-European ☐ Paleo-Indian ☐ Archaic ☐ Woodland [	Contact	
	1730-1770± Intensified a 1770-1830± Early Indus 1830-1880± Industrializa 1880-1940± Urbanizatio	and Frontier Settlement and Durable Occupation	n
b) Geographical zone	Lower F	'eninsula <sup>p</sup> eninsula/Cypress Swamp	
c) Historic period them	e(s)		
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	<b>=</b>	nd Demographic Changes ring and Decorative Arts ions ations
	USE BLA	CK INK ONLY	crs-1

CRS# N-14142

9. OTHER NOTES OR OBSERVATIONS:



# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	N-14142	
------	---------	--

	ADDRESS/LOCATION: 1453 Church Road
!.	FUNCTION(S): historic Single family dwelling current Single family dwelling
	YEAR BUILT: 1954 CIRCA?: ARCHITECT/BUILDER: Unknown
,	STYLE OR FLOOR PLAN: Post-World War II vernacular
<b>.</b>	INTEGRITY: original site ⊠ moved □
	if moved, from where other location's CRS # year
	list major alterations and additions with years (if known)  a. b.
<b>.</b>	CURRENT CONDITION: excellent  good  fair  poor
·-	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	<ul> <li>a. Overall shape: Rectangular with addition to the Stories: 1 south</li> <li>Additions: None</li> </ul>
	b Structural system (if known): Balloon frame
	c. Foundation: materials: Poured concrete basement: full ⊠ partial □ not visible □ no basement □
	d. Exterior walls (original if visible& any subsequent coverings): Aluminum siding
	e. Roof: shape: Side gable materials: Asphalt shingle cornice: Returns dormers: None chimney: location(s): Brick interior; centered rear of roof
<b>;</b> .	DESCRIPTION OF ELEVATIONS:
	a. Facade: Direction: W 1) Bays 3 2) Windows 3 fenestration Symmetrical type Bay window with fixed central and 1/1 wood side sashes; 1/1 wood sash grouped in pairs trim None

	Facad 3)	de (cont'd) Door(s) location	1
		Door(s)	
	•	location	
			Centered
		type	Solid wood with single fixed diamond light
		trim	None
	4)	Porch(es)	Poured concrete stoop
b.	Side:	Direction: N	
	1)	Bays	2
	2)	Windows	2
		fenestration	n Regular
		type	1/1 double-hung wood sash with vinyl storm windows
		trim	None
		shutters	None
	3)	Door(s)	None
		location	N/A
		type	N/A
		trim	N/A
	4)	Porch(es)	None
C.	Side:	Direction: S	
	1}	Bays	2
	2)	Windows	3
		fenestration	· ·
		type	1/1 metal sash and single light, top-hinged jalousie windows
		trim	None
		shutters	None
	3)	Door(s)	1 on enclosed porch
		location	Centered on porch
		type	Aluminum and glass storm door (only door visible)
		trim	None
	4)	Porch(es)	Single bay, 1-story with jalousie windows and shed roof
d.		Direction: E	
	1)	Bays	Not visible
	2)	Windows	Not visible
		fenestration	
		type	Not visible
		trim	Not visible
	~ \	shutters	Not visible
	3)	Door(s)	Not visible
		location	Not visible
		type	Not visible
	45	trim	Not visible
	4)	Porch(es)	Not visible

- 9. INTERIOR: Not accessible
- 10. LANDSCAPING: Set back from the road on a small, landscaped bench; behind (to east) is a late 20th century housing development
- 11. OTHER COMMENTS: Construction date from tax assessment records



## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-14142

1.	ADDRESS/LOCATION: 1453 Church Road	
2.	FUNCTION(S): historic Garage current Garage	<u> </u>
3.	YEAR BUILT: 1955 CIRCA?: X ARCHITECT/BUILDER: Unknown	_ <del>_</del>
4.	STYLE/FLOOR PLAN: 1-story, 1-bay with shallow shed roof	
5.	<b>.</b>	at <u>ion's CRS</u> # <u>year</u>
	list major alterations and additions with years (if known)  a.  b.	уе <u>а</u> г
6.	CURRENT CONDITION: excellent \( \sum \) good \( \sum \) fai	ir 📋 poor 🗀
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1	
	c. Wali coverings Concrete block	
	d. Foundation Concrete block	
	e. Roof structural system Frame coverings Not Visible openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul><li>a. Facade: direction: W</li><li>1) bays: 1</li><li>2) windows: None</li></ul>	
	3) door(s): Wood garage door with 3 fixed lights	
	4) other: N/A	

			CRS#	N-14142
	b.	Side: direction: S 1) bays: 2		
		2) windows: None		
		3) door(s): None		
		4) other: N/A		
	c.	Side: direction: N		
		1) bays: 2 2) windows: Not visible		
		3) door(s): Not visible		
		4) other: Not visible		
	d.	Rear: direction: E 1) bays: 1		
		2) windows: Not visible		
		3) door(s): Not visible		
		4) other: Not visible		
9.	INTE	RIOR (if accessible):		
	a) Flo	or plan Not accessible		
	b) Pa	rtition/walls Not accessible		
	c) Fin	ishes Not accessible		

d) Furnishings/machinery Not accessible

## CULTURAL RESOURCE SURVEY MAP FORM

CRS # <u>N-14142</u>\_\_\_

1.	ADDRESS/LOCATION:	1453 Church Road				
----	-------------------	------------------	--	--	--	--


2. NOT FOR PUBLICATION reason: \_\_\_\_\_ \_\_ \_\_\_ \_\_\_ \_\_\_\_ \_\_\_\_ \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN



### **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

### PHOTOGRAPHIC INVENTORY

CRS# <u>N-14142</u>	Date	9/2003	Photo Roll#	_C <u>-4536</u>	Surveyor	Gerald Kuncio		
Description 13 - Facade and north side, facing SE; 14 - Facade, south side, and garage, facing NE								
Negative location (if other than SHPO)								
Attach contact print(s):								



crs-13

doc # 20-06-01-05-12

		_
		-
		_
		-
		_
		_
		_
		-
		_
		_
		_
		_
		_
		-
		_

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS # N-14143

SPO Map Hundred

06.07.32 New Castle

Quad

St. Georges

Other

10-049-00025

1.	HISTORIC NAME/FUNCTION:	Owelling, 1503 Church Road					
2.	ADDRESS/LOCATION: 1503 C	hurch Road (East Side)	_				
3.	TOWN/NEAREST TOWN: Bear			vicinity? 🛚			
4.	MAIN TYPE OF RESOURCE:	MAIN TYPE OF RESOURCE: building \( \text{Substitute} \) structure \( \text{Substitute} \) site \( \text{Substitute} \) object \( \text{Substitute} \)					
5.	MAIN FUNCTION OF PROPERTY	:Dwelling_					
6.	PROJECT TITLE/ REASON FOR SURVEY (if applicable): Church Road (Wynnefield to S.R. 71) Improvements						
7. ,	ADDITIONAL FORMS USED:						
	#: Form:	List property types:					
	1 CRS 2 Main Building Form						
	0 CRS 3 Secondary Building Form						
	0 CRS 4 Archaeological Site						
	0 CRS 5 Structure (Building						
	0 CRS 6 Structure (Land Fea	iture) Form					
	0 CRS 7 Object Form	·					
	0 CRS 8 Landscape Element	s Form					
	1 CRS 9 Map Form	N/A					
	0 CRS 14 Potential District F	orm					
	SURVEYOR INFORMATION:	Caralid M. Karasia					
	Surveyor name: Gerald M. Kuncio						
Principal Investigator name: Gerald M. Kuncio							
	Principal Investigator signature:						
	Organization:	Skelly and Loy, Inc.	Date:	9/2/2003			

Dwelling constructed du	uring the post-World War II e	ега			
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check a	Il appropriate boxes; refer to state management			
a) Time period(s)	Pre-European Col	ntact			
	☐ Archaic ☐ Woodland I				
	Woodland II				
	1600-1750± Contact Period 1630-1730± Exploration and	d Frontier Settlement			
	1730-1770 telepsified and 1770-1830 Early Industrial	ization			
	1830-1880± Industrialization 1880-1940± Urbanization as				
$\boxtimes$	1940-1960 Suburbanizatio	n and Early Ex-urbanization			
b) Geographical zone	Coastal	nsula insula/Cypress Swamp r of Wilmington)			
c) Historic period theme(s)					
	Agriculture [Forestry	☐ Transportation and Communication ☐ Settlement Patterns and Demographic Changes			
Ä	Trapping/Hunting [	Architecture, Engineering and Decorative Arts  Government			
	Mining/Quarrying Fishing/Oystering	Religion			
	Manufacturing Retailing/Wholesaling	Education Community Organizations			
	Finance [ Professional Services [	<ul> <li>Occupational Organizations</li> <li>Major Families, Individuals and Events</li> </ul>			

9. OTHER NOTES OR OBSERVATIONS:

CRS# N-14143



# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-14143

1.	ADDRESS/LOCATION: 1503 Church Road						
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling						
3.	YEAR BUILT: 1953 CIRCA?: ARCHITECT/BUILDER: Unknown						
4.	STYLE OR FLOOR PLAN: Post-World War II vernacular with Cape Cod elements						
5.	INTEGRITY: original site 🗵 moved 🔲						
	if moved, from where other location's CRS #	<u>уеаг</u>					
	list major alterations and additions with years (if known)	үеаг					
	a.	<u>Year</u>					
	<u>b.</u>						
<b>6</b> .	CURRENT CONDITION: excellent  good  fair poor						
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave blanks.)	no					
	a. Overall shape: Rectangular Stories: 1						
	Additions: None						
	b Structural system (if known): Balloon frame						
	c. Foundation: materials: Poured concrete						
	basement: full 🛛 partial 🔲 not visible 🗍 no basement 🗍						
	d. Fotodo con lle designative de la consequence della consequence						
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding						
	e. Roof: shape: Side gable						
	materials: Asphalt shingle						
	cornice: Open						
	dormers: 1 - Rear, centered with a shed roof						
	chimney: location(s): Brick exterior; south elevation						
8.	DESCRIPTION OF ELEVATIONS:						
	a. Facade: Direction: W						
	1) Bays 3						
	2) Windows 2						
	fenestration Regular						
	type 1/1 wood sash						
	trîm Plain wood frames shutters None						
	Shutters none						

```
Facade (cont'd)
          Door(s)
              location
                          Centered
             type
                          Wood raised panel
             trim
     4)
          Porch(es)
                          1-story, 1-bay with wood floor, lattice balustrade, round metal columns, and
          flat roof
     Side: Direction: N
b.
                         2
     1)
          Bays
     2)
          Windows
                         2
             fenestration Regular
                         1/1 double-hung wood sash
             trim
                         None
             shutters
                         None
     3)
                         None
          Door(s)
             location
                         N/A
             type
                         N/A
                         N/A
             trim
     4)
          Porch(es)
                         None
c.
    Side: Direction: S
     1)
          Bays
                         2
    2)
          Windows
                         1
             fenestration kregular
                         1/1 double-hung wood sash
             trim
                         None
             shutters
                         None
    3)
          Door(s)
                         None
             location
                         N/A
             type
                         N/A
                         N/A
             trim
    4)
          Porch(es)
                         None
    Rear: Direction: E
d.
    1)
          Bays
                         Not visible
    2)
          Windows
                         Not visible
             fenestration Not visible
             type
                         Not visible
             trim
                         Not visible
             shutters
                         Not visible
    3)
          Door(s)
                         Not visible
             location
                         Not visible
                         Not visible
             type
                         Not visible
             trim
```

9. INTERIOR: Not accessible

Porch(es)

4)

- 10. LANDSCAPING: Set back from the road on a flat, landscaped yard with scattered trees
- 11. OTHER COMMENTS: Construction date from tax assessment record

Not visible

# CULTURAL RESOURCE SURVEY MAP FORM

CRS# N-14143


1.	ADDRESS/LOCATION:	1503 Church Road
	NOT FOR DURI ICATION	

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

#### INDICATE NORTH ON SKETCH



## INDICATE NORTH ON PLAN

NOT TO SCALE	W-I W-I TW	TDOOR	DRIVEWAY
	<u> </u>		

## **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

## PHOTOGRAPHIC INVENTORY

CRS#	N-14143	Date	9/2003	_ Photo Roll#	C-4536	Surveyor	Gerald Kuncio
Descrip	tion 17 - Facade	and no	rth side, fac	ing SE			
<sup>—</sup> Negativ	e location (if othe	r than S	SHPO)				
_ Attach c	contact print(s):						

crs-13

ndoc # 20-06-01-05-12

			-
			_
			-
			-
			_
			_
			_
			_
			_
			_
			-
			-
			_
			-
			_
			-
			_

# A Significant

## DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

1,	HISTORIC NAME/FUNCTION:	Dwelling, 1494	Church Road				
2.	ADDRESS/LOCATION: 1494 C	hurch Road (W	lest Side)				
3.	TOWN/NEAREST TOWN: Bear				v	icinity?	$\boxtimes$
4.	MAIN TYPE OF RESOURCE:	building landscape		ucture 🔲 listrict 🔲	site 🗌	objec	t 🗆
5.	MAIN FUNCTION OF PROPERTY	: Dwelling				-	
6.	PROJECT TITLE/ REASON FOR S Church Road (Wynnefield to S.R.  ADDITIONAL FORMS USED:						
۲.	ADDITIONAL FORMS USED:						
	#: Form:		List property t	/p <u>e</u> s:		_	
	1 CRS 2 Main Building Form		Dwelling				
	0 CRS 3 Secondary Building						
	0 CRS 4 Archaeological Site						
	0 CRS 5 Structure (Building						
	0 CRS 6 Structure (Land Fea	ature) F <u>orm</u>			_		
	0 CRS 7 Object Form						-
	0 CRS 8 Landscape Element 1 CRS 9 Map Form		N/A				
	0 CRS 14 Potential District F						
8.	SURVEYOR INFORMATION:						
	Surveyor name:	Gerald M. Ku	nclo				
	Principal Investigator name:	Gerald M. Ku	ncio				
	Principal Investigator signature:						
	Organization:	Skelly And Lo	oy, Inc.		Date:	9/2/2003	

Dwelling constructed d	uring the post-World Wa	r II era	
0. STATE HISTORIC CONT lan(s}):	EXT FRAMEWORK (chec	ck all appropriate boxes; refer to sta	te management
• • •	Pre-European	Contact	
a) Time period(s)	☐ Paleo-Indian ☐ Archaic		
	Woodland I		
	Woodland II 1600-1750	riod (Native American)	
	1630-1730± Exploration	and Frontier Settlement	
	1770-1830 ± Early Indust		
		ation and Early Urbanization n and Early Suburbanization	
☒		ation and Éarly Ex-urbanization	
b) Geographical zone	Piedmo	nt	
	<u> </u>	'eninsula 'eninsula/Cypress Swamp	
	☐ Coastal	City of Wilmington)	
c) Historic period them		•	
, ········· <b>F</b> ·······	Agriculture	☐ Transportation and Commu	nication
ğ	Forestry	Settlement Patterns and Der	nographic Changes
	Trapping/Hunting Mining/Quarrying	<ul><li>Architecture, Engineering ar</li><li>Government</li></ul>	id Decorative Arts
	Fishing/Oystering Manufacturing	Religion Education	
Ĭ	Retailing/Wholesaling	Community Organizations	
	Finance Professional Services	<ul> <li>Occupational Organizations</li> <li>Major Families, Individuals a</li> </ul>	
		24 BH 250 V	crs-1
	USE BLA	CK INK ONLY	CRS. I

**USE BLACK INK ONLY** 

CRS# N-14144

9. OTHER NOTES OR OBSERVATIONS:

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS # N-14144

	4597	
1.	ADDRESS/LOCATION: 1494 Church Road	_
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling	
3.	YEAR BUILT: 1954 CIRCA?:  ARCHITECT/BUILDER: Unknown	<del>_</del>
4.	STYLE OR FLOOR PLAN: Post-World War II vernacular with Cape Cod elements	
5.	INTEGRITY: original site	<u>year</u>
	list major alterations and additions with years (if known)  a. Garage expanded and altered, with entrance now on Smith Street  b.	<u>year</u>
6.	CURRENT CONDITION: excellent  good  fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leaviblanks.)	e no
	<ul> <li>a. Overall shape: Original: Rectangular; Stories: 11/2</li> <li>Current: L-shaped</li> <li>Additions: Garage converted to 2-bays and room added to its rear; also attached to the house</li> </ul>	e
	b Structural system (if known): Balloon frame	
	c. Foundation: materials: Poured concrete basement: full ⊠ partial □ not visible □ no basement □	
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding	
	<ul> <li>e. Roof: shape: Side gable on original; gable end on addition materials: Asphalt shingle cornice: Open dormers: 1 - South side of the main block; does not appear to be original chimney: location(s): Brick interior; just north of center, below the ridge line</li> </ul>	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: Direction: E</li> <li>1) Bays 4 on the original portion, plus a hyphen and one on the former garage</li> <li>2) Windows 4         fenestration irregular         type 1/1 double-hung wood sash and three part picture window with vertical dividers         trim None         shutters Fixed, decorative vinyl</li> </ul>	

Facade (cont'd)

Door(s)

location Second bay from the north type Wood with raised panels

trim None

4) Porch(es) 1 1/2 bays with concrete floor, metal supports, shed roof

b. Side: Direction: S

1) Bays 4 (Garage and rear addition)

2) Windows 1

fenestration irregular

type 1/1 double-hung wood sash

trim None shutters None or(s) 2

3) Door(s)

location East end of wall

type Vinyl garage doors with four fixed lights (sunburst pattern) in each

trim None

4) Porch(es) None

c. Side: Direction: N

1) Bays Not visible
2) Windows Not visible
fenestration Not visible
type Not visible
trim Not visible
shutters Not visible

shutters Not visible
3) Door(s) Not visible
location Not visible
type Not visible
trim Not visible

4) Porch(es) Not visible

d. Rear: Direction: W

1) Bays 4

2) Windows 4

fenestration Regular

type 1/1 Double-hung wood sash

trim None shutters None 3) None Door(s) N/A location N/A type trím N/A Porch(es) 4) None

9. INTERIOR: Not accessible

10. LANDSCAPING: Set near the road with a small setback of lawn and trees

11. OTHER COMMENTS: Construction date from tax assessment records

## CULTURAL RESOURCE SURVEY MAP FORM


1.	ADDRESS/LOCATION:	1494 Church Road
2.	NOT FOR PUBLICATION	reason:

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

#### INDICATE NORTH ON SKETCH



# INDICATE NORTH ON PLAN NOT TO SCALE wН CHIMNEY ROAD HOUSE SMITH GARAGE D-**HOOOR** DRIVEWAY CHURCH ROAD N-14144

## DELAWARE STATE HISTORIC PRESERVATION OFFICE

## PHOTOGRAPHIC INVENTORY

CRS#	N-14144	Date	9/2003	Photo Roll#	C-4536	Surveyor	Gerald Kuncio
Descript NW	tion 18 - Facade,	hypher	n, and forme	er garage, facinç	g W; 19 - 0	Garage and	south side, facing
Negativ	e location (if othe	r than S	HPO)				
- Attach c	contact print(s):						
<b>-</b>							

dac # 20-06-01-05-12

**CRS-13** 

		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		<b>-</b>
		-
		_
		_
		_
		_
 	 <del>.</del>	

# Ant IN THE SECOND

## DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

1.	ні\$т	ORIC NAME/FUNCTION:	Dwelling, 1502 Church Road			
2.	ADDF	RESS/LOCATION: _1502 C	hurch Road (West Side)			
3.	TOWN	N/NEAREST TOWN: Bear		_ vicinity? 🗵		
4.	MAIN	MAIN TYPE OF RESOURCE: building Structure site landscape district				
5.	MAIN	FUNCTION OF PROPERTY	: Dwelling	-		
6.		ECT TITLE/ REASON FOR S th Road (Wynnefield to S.R.				
7.	ADDITIO	ONAL FORMS USED:				
	#:	Form:	List property types:			
	1	CRS 2 Main Building Form	Dwelling			
	0	CRS 3 Secondary Building	Form			
	0	CRS 4 Archaeological Site	Form			
	0	CRS 5 Structure (Building	-Like) Form			
	C	CRS 6 Structure (Land Fed	iture) Form			
	0	CRS 7 Object Form	<u> </u>			
	0	CRS 8 Landscape Elemen	ts Form			
	1	CRS 9 Map Form	N/A	-		
	0	CRS 14 Potential District F	orm			
8.	SURVE	YOR INFORMATION:				
	Surveyo	or name:	Gerald M. Kuncio			
	Principa	al Investigator name:	Gerald M. Kuncio			
	Princip	al Investigator signature:				
	Organiz	zation:	Skelly and Loy, Inc.	te: <u>9/2/2003</u>		

Dwelling constructed d	uring the post-World War I	ll era	
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check	all appropriate boxes; refer t	o state management
a) Time period(s)	Pre-European C Paleo-Indian	Contact	
	🔲 Archalc		
	☐ Woodland I ☐ Woodland II		
H	1600-1750± Contact Period 1630-1730± Exploration a		
	1730-1770± Intensified ar 1770-1830± Early Industr	nd Durable Occupation	
	1830-1880± Industrializat	ion and Early Urbanization	
		and Early Suburbanization tion and Early Ex-urbanization	1
b) Geographical zone	Piedmon		
		ninsula eninsula/Cypress Swamp	
	☐ Coastal ☐ Urban (C	ity of Wilmington)	
c) Historic period them	e(s)		
	Agriculture Forestry	☐ Transportation and Co	mmunication d Demographic Changes
	Trapping/Hunting Mining/Quarrying		ing and Decorative Arts
블	Fishing/Oystering	Religion	
	Manufacturing Retailing/Wholesaling	Education Community Organization	
	Finance Professional Services	<ul><li>Occupational Organiza</li><li>Major Families, Individu</li></ul>	
	Heren Ac	K INK ON A	crs-1
	USE BLAU	K INK ONLY	CK9- I

CRS# N-14145

9. OTHER NOTES OR OBSERVATIONS:



# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-14145

	The state of the s	
1.	ADDRESS/LOCATION: 1502 Church Road	
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling	
3.	YEAR BUILT: 1952_ CIRCA?: ARCHITECT/BUILDER: Mr. Smith	
4.	STYLE OR FLOOR PLAN: Post-World War II vernacular	
5.	INTEGRITY: original site ⊠ moved □	
	if moved, from where other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known)  a. Vinyl siding, addition on north side  b.	<u>year</u>
6.	CURRENT CONDITION: excellent 🛛 good 🗌 fair 🗌 poor 🗀	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave blanks.)	no
	a. Overall shape: L-shaped with side addition Stories: 1 Additions: 1-Story, 1-bay on north side	
	b Structural system (if known): Balloon frame	
	c. Foundation: materials: Poured concrete basement: full ⊠ partial □ not visible □ no basement □	
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding	
	e. Roof: shape: Side gable; gable end over the ell materials: Asphalt shingle cornice: Open dormers: None chimney: location(s): Metal exterior; between original north side and addition	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: Direction: E 1) Bays 3 2) Windows 3 fenestration Irregular type 1/1 sash grouped singly and in pairs trim None shutters Fixed decorative vinyl	

```
Façade (cont'd)
          Door(s)
     3)
                         1
             location
                         Slightly off center
             type
                         Wood raised panel
                         Plain wood frame
             trim
     4)
          Porch(es)
                         Brick front stoop
     Side: Direction: N
b.
                         2
     1)
          Bavs
     2)
          Windows
                         2
             fenestration Paired
                         1/1 double-hung wood sash
             type
             trim
                         None
             shutters
                         None
     3)
                         None
          Door(s)
                         N/A
             location
             type
                         N/A
                         N/A
             trim
     4)
          Porch(es)
                         None
    Side: Direction: S
          Bays
                         3 - 1 house, 2 garage
     1)
     2)
          Windows
             fenestration Single
             type
                         1/1 double-hung wood sash
             trim
                         None
             shutters
                         None
                         None
    3)
          Door(s)
                         N/A
             location
                         N/A
             type
                         N/A
             trim
    4)
          Porch(es)
                         None
    Rear: Direction: W
d.
          Bays
    1)
                         3 - 2 house, 1 garage
    2)
          Windows
             fenestration Regular
             type
                         6/6 double-hung wood sash and 1/1 double-hung wood sash
             trim
                         None
             shutters
                         None
     3)
          Door(s)
             location
                         North side of the garage and slightly off center of the main block
             type
                         Metal with 12 fixed lights (both)
```

9. INTERIOR: Not accessible

4)

trim

Porch(es)

- 10. LANDSCAPING: Set back from the road on a flat, landscaped yard with scattered shrubbery
- 11. OTHER COMMENTS: Construction date provided by the owner

None


Deck with wood deck, picket railing, and lattice skirt

## **CULTURAL RESOURCE SURVEY** MAP FORM


N-14145 CRS#

1.	ADDRESS/LOCATION: _1502 Church Road
2.	NOT FOR PUBLICATION
3.	LOCATION MAP:
	Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
	(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN



## **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

## PHOTOGRAPHIC INVENTORY

CRS # N-1414 <u>5</u>	Date _ <u>9/2</u> 003	Photo Roll #	C-45 <u>36</u> Sur	veyor Gerald <u>Ku</u> r	ncio
_ Description 20 -Fac	cade and north side, fac	cing SW; 21 - Rea	ar and north sid	e, facing SE	
_Negative location (if	other than SHPO) _				
Attach contact print	(s):				
<del>-</del>					

\_ doc # 20-06-01-05-12

**crs-13** 

	_
	_
	_
	_
	_
	_
	-
	_
	_
	_
	_
	-
	_
	<b></b> -
	-
	-

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-14146
SPO Map	06.07.32
Hundred	New Castle
Quad	St. Georges
Other	10-053 2-0002

1.	HISTORIC NAME/FUNCTION: Dwe	elling, 1508 Church Road					
2.	ADDRESS/LOCATION: 1508 Chur	ADDRESS/LOCATION: 1508 Church Road (West Side)					
3.	TOWN/NEAREST TOWN: Bear			vicinity? 🖂			
4.		building 🛭 structure andscape 🗌 distric		te 🗌 object 🔲			
5.	. MAIN FUNCTION OF PROPERTY:	Dwelling					
6.	PROJECT TITLE/ REASON FOR SUF Church Road (Wynnefield to S.R. 71						
7.	ADDITIONAL FORMS USED:						
	#: Form:	List property types:					
	1 CRS 2 Main Building Form	Dwelling					
	0 CRS 3 Secondary Building Fo	rm					
	0 CRS 4 Archaeological Site Fo						
	0 CRS 5 Structure (Building-Like						
	0 CRS 6 Structure (Land Featur	re) Form					
	0 CRS 7 Object Form	_					
	0 CRS 8 Landscape Elements F						
	1 CRS 9 Map Form	N/A					
	0 CRS 14 Potential District Form	<u> </u>					
8.	SURVEYOR INFORMATION:						
	Surveyor name: G	erald M. Ku <u>ncio</u>					
	Principal Investigator name:G	erald M. Kuncio					
	Principal Investigator signature:						
	Organization: S	kelly and Loy, Inc.		Date: 9/2/2003			

Dwelling constructed during the post-World War II era			
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check all appropriate boxes; refer to state management		
a) Time period(s)	Pre-European Contact		
, , , , , ,	☐ Paleo-Indian ☐ Archaic		
	☐ Woodland I		
Д	1600-1750± Contact Period (Native American)		
Ë	1630-1730± Exploration and Frontier Settlement 1730-1770± Intensified and Durable Occupation		
	1770-1830』 Early Industrialization 1830-1880』 Industrialization and Early Urbanization		
	1880-1940± Urbanization and Early Suburbanization 1940-1960± Suburbanization and Early Ex-urbanization		
b) Geographical zone	☐ Piedmont		
	☑ Upper Peninsula ☐ Lower Peninsula/Cypress Swamp		
	☐ Coastal ☐ Urban (City of Wilmington)		
c) Historic period them	e(s)		
	Agriculture		
	Forestry Settlement Patterns and Demographic Changes Trapping/Hunting Architecture, Engineering and Decorative Arts		
	Mining/Quarrying Government Fishing/Oystering Religion		
	Manufacturing		
Ä	Finance		
	Troidestonal Services   major Families, individuals and Events		

9. OTHER NOTES OR OBSERVATIONS:

CRS# N-14146



## CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	N-14146	
------	---------	--

1.	ADDRESS/LOCATION: 1508 Church Road
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling
3.	YEAR BUILT: 1945_ CIRCA?: ARCHITECT/BUILDER: Unknown
4.	STYLE OR FLOOR PLAN: Cape Cod
5.	INTEGRITY: original site ⊠ moved □
	if moved, from where other location's CRS # year
	list major alterations and additions with years (if known)  a. b.
6.	CURRENT CONDITION: excellent  good  fair poor
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	a. Overall shape: Rectangular with hyphen and Stories: 2 attached garage Additions: None
	b Structural system (if known): Balloon frame
	c. Foundation: materials: Poured concrete basement: full ⊠ partial □ not visible □ no basement □
	d. Exterior walls (original if visible& any subsequent coverings): Asbestos shingle siding
	e. Roof: shape: Side gable, steeply pitched materials: Asphalt shingle cornice: Open dormers: 2 gable end roof dormers over the facade chimney: location(s): Brick exterior; north elevation
8.	DESCRIPTION OF ELEVATIONS:
	<ul> <li>a. Facade: Direction: E</li> <li>1) Bays 3</li> <li>2) Windows 2 on main block, 2 in hyphen; four on each garage door fenestration Symmetrical</li> <li>type House: 6/6 double-hung wood frame and picture window w/fixed middle sash and 2/2 double-hung wood side sash; Hyphen: 1/1 sash; Garage doors: 4 fixed lights each</li> </ul>

Fixed, decorative vinyl on house windows

trim

shutters

None

```
Facade (cont'd)
          Door(s)
             location
                         Centered on facade and hyphen
             type
                         House: Wood, 4 recessed panels and six fixed lights; Hyphen: Metal with two
          raised panels under 1 fixed light
                         House: Plain wood frame
             trim
                         House: Stoop with 2 brick steps, brick floor, and lattice wood side railings
    4)
          Porch(es)
b.
    Side: Direction: S
                         3
     1)
          Bays
    2)
          Windows
                         1
             fenestration Regular
                         6/6 double-hung wood sash
             type
             trim
                         None
                         None
             shutters
    3)
          Door(s)
                         None
             location
                         None
             type
                         N/A
                         N/A
             trim
    4)
          Porch(es)
                         None - Hyphen
    Side: Direction: N
          Bays
                         3
    1)
          Windows
                         2
    2)
             fenestration Regular
             type
                         6/6 double-hung wood sash
             trim
                         None
                         None
             shutters
    3)
                         None
          Door(s)
             location
                         N/A
                         N/A
             type
                         N/A
             trim
    4)
          Porch(es)
                         None
    Rear: Direction: W
d.
          Bays
    1)
    2)
          Windows
                         Not visible
             fenestration Not visible
             type
                         Not visible
             trim
                         Not visible
             shutters
                         Not visible
    3)
          Door(s)
                         Not visible
             location
                         Not visible
                         Not visible
             type
                         Not visible
```

9. INTERIOR: Not accessible

4)

trim

Porch(es)

- LANDSCAPING: Set back from the road on a flat, landscaped yard
- 11. OTHER COMMENTS: Construction date from tax assessment records

Not visible

#### **CULTURAL RESOURCE SURVEY** MAP FORM

CRS#	N-14146	
<b>3</b> 11 <b>3</b> 17		

1.	ADDRESS/LOCATION:	1508 Church Road	
2.	NOT FOR PUBLICATION	reason:	


**LOCATION MAP:** 3.

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

reason:

#### INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN



## DELAWARE STATE HISTORIC PRESERVATION OFFICE

## PHOTOGRAPHIC INVENTORY

- CRS#	N-14146	Date <u>9/2003</u>	_ Photo Roll#	C-4536	Surveyor	Gerald Kuncio
<sup>—</sup> Descript	tion 22 - Facade,	, hyphen, and gara	ge, facing NW			
_ Negative	e location (if othe	r than SHPO)				
_Attach c	contact print(s):					
-			0 6		•	

doc # 20-06-01-05-12

**crs-13** 

		-
		_
		_
		_
		-
		_
		~
		_
		-
		_
		-
		_

# STEST ON 1910

## DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

LUCTODIO MANICICUNISTICAL. D. P. 4547 Object Dec.	Other	10-049-0016.3, _0016.4, 0002 <u>6</u>
HISTORIC NAME/FUNCTION:Dwelling, 1517 Church Road		
ADDRESS/LOCATION: 1517 Church Road (East Side)		
TOWN/NEAREST TOWN: Bear		vicinity? 🖂
MAIN TYPE OF RESOURCE: building 🔀 structure 🗌 landscape 🗍 district 🗍	site	object 🗍
MAIN FUNCTION OF PROPERTY:		
PROJECT TITLE/ REASON FOR SURVEY (if applicable): Church Road (Wynnefield to S.R. 71) Improvements		
#: Form: List property types: 1 CRS 2 Main Building Form Dwelling		
0 CRS 3 Secondary Building Form 0 CRS 4 Archaeological Site Form		
0 CRS 4 Archaeological Site Form 0 CRS 5 Structure (Building-Like) Form		
0 CRS 6 Structure (Land Feature) Form		
0 CRS 7 Object Form		
0 CRS 8 Landscape Elements Form		
1 CRS 9 Map Form N/A		
0 CRS 14 Potential District Form		
SURVEYOR INFORMATION:		
Surveyor name: Gerald M. Kuncio		
Principal Investigator name: Gerald M. Kuncio		
Principal Investigator signature:		
Organization: Skelly and Loy, Inc.	7	ate: 9/2/2003

Dwelling constructed during the post-World War II era						
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (chec	k all appropriate boxes; refer	to state management			
a) Time period(s)	Pre-European Paleo-Indian Archaic Woodland I Woodland II	Contact				
	1880-1940 ± Urbanization	and Frontier Settlement and Durable Occupation	п			
b) Geographical zone	Lower P	nt eninsula eninsula/Cypress Swamp City of Wilmington)				
c) Historic period theme	e(s)					
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	=	id Demographic Changes ing and Decorative Arts ons itions			
	USE BLAC	CK INK ONLY	crs-1			

CRS# N-14147

9. OTHER NOTES OR OBSERVATIONS:

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-14147

1.	ADDRESS/LOCATION: 1517 Church Road						
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling						
3.	YEAR BUILT: 1954 CIRCA?: ARCHITECT/BUILDER: Mr. Smith	_					
4.	STYLE OR FLOOR PLAN: Mid-20th century vernacular	_					
<b>5</b> .	INTEGRITY: original site	<u>year</u>					
	list major alterations and additions with years (if known)  a. Porch, siding, and dormers do not appear to be original  b.	year					
6.	CURRENT CONDITION: excellent 🗌 good 🛛 fair 🗍 poor 🗋						
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)						
	a. Overall shape: Rectangular Stories: 2 Additions: Dormers do not appear to be original						
	b Structural system (if known): Balloon frame						
	c. Foundation: materials: Poured concrete basement: full ⊠ partial ☐ not visible ☐ no basement ☐						
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding						
	e. Roof: shape: Original: hip; 3-bay roof dormers added to each side materials: Asphalt shingle cornice: Open dormers: 3-bay roof dormers chimney: location(s): Exterior and covered with vinyl; south side						
8.	DESCRIPTION OF ELEVATIONS:						
	<ul> <li>a. Facade: Direction: W</li> <li>1) Bays 3</li> <li>2) Windows 5</li> <li>fenestration lrregular</li> <li>type 3-light casement window; 3 - 1/1 vinyl sash on enclosed porch; 1/1 do hung wood</li> <li>trim None</li> <li>shutters None</li> </ul>	uble-					

```
Facade (cont'd)
          Door(s)
             location
                         Porch - south side; House - centered
                         Porch - wood paneled with 1 fixed light and metal exterior screen; House- Not
             type
          visible
                         None
             trim
          Porch(es)
                         1-Story, 1-bay enclosed with shed roof, 1/1 vinyl sash, brick walls, concrete
     4)
          block foundation
b.
     Side: Direction: N
          Bays
                         4
     1)
     2)
          Windows
                         4
             fenestration Regular
                         1/1 double-hung wood sash
             type
                         None
             trim
             shutters
                         None
     3)
                         None
          Door(s)
                         N/A
             location
                         N/A
             type
                         N/A
             trim
                         None
     4)
          Porch(es)
    Side: Direction: S
     1)
          Bays
    2)
          Windows
             fenestration Regular
                         1/1 double-hung wood sash
             type
             trim
                         None
                         None
             shutters
                         None
     3)
          Door(s)
                         N/A
             location
                         N/A
             type
                         N/A
             trim
                         None
          Porch(es)
     4)
d.
     Rear: Direction: E
     1)
          Bays
                         Not visible
     2)
          Windows
             fenestration Not visible
                         Not visible
             type
             trim
                         Not visible
                         Not visible
             shutters
                         Not visible
     3)
          Door(s)
             location
                         Not visible
             type
                         Not visible
                         Not visible
             trim
                         Not visible
     4)
          Porch(es)
```

- 9. INTERIOR: Not accessible
- 10. LANDSCAPING: Set back slightly from the road with large pine trees in the front
- 11. OTHER COMMENTS: Construction date from tax assessment records

## **CULTURAL RESOURCE SURVEY** MAP FORM

N-14147 CRS#


1.	ADDRESS/LOCATION:	1517 Church Road	
2	NOT FOR PURI ICATION		

**LOCATION MAP:** 


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



### INDICATE NORTH ON PLAN



# DELAWARE STATE HISTORIC PRESERVATION OFFICE

# PHOTOGRAPHIC INVENTORY

CRS#	<u>N-14</u> 1 <u>47</u>	_ Date	9/2003	Photo Roll #	C-4536	Surveyor	Gerald Kuncio
<del>-</del> '	tion 23 - North s e and <u>south s</u> ide		_	s, facing SE; 24	- Facade	and south	side, facing NE; 25
_Negativ	e location (if othe	er than S	SHPO)	_			
Attach o	contact print(s):						

\_ doc # 20-06-01-05-12

**CRS-13** 

		-
		_
		_
		_
		-
		_
		_
		_
		-
		_
		_
		_
		_
		_
		_
		_
		_

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

		_	
I. HISTORIC NAME/FUNCTION:	Dwelling, 1527 Church Road		
2. ADDRESS/LOCATION: 1527 C	Church Road (East Side)		
B. TOWN/NEAREST TOWN: Bear			vicinity? 🛚 🖂
. MAIN TYPE OF RESOURCE:	building ⊠ structure [ landscape ☐ district [	site 🗌	object 🗌
MAIN FUNCTION OF PROPERT	Y: <u>Dwell</u> ing		
. PROJECT TITLE/ REASON FOR Church Road (Wynnefield to S.F.			
#: Form:	List property types:		
1 CRS 2 Main Building For			<del>-</del>
1 CRS 3 Secondary Buildin			
0 CRS 4 Archaeological Sit			-
0 CRS 5 Structure (Building	y-Like) Form		
0 CRS 6 Structure (Land Fe	eature) Form		
0 CRS 7 Object Form			
0 CRS 8 Landscape Elemer	nts Form		
1 CRS 9 Map Form	N/A		
0 CRS 14 Potential District	<u>Form</u>		
. SURVEYOR INFORMATION:			
Surveyor name:	Gerald M. Kuncio		
Principal Investigator name:	Gerald M. Kuncio		
Principal Investigator signature:		<u> </u>	
Organization:	Skelly and Loy, Inc.	Date:	9/2/2003

Dwelling constructed do	ıring the post-World War II	era
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check	all appropriate boxes; refer to state management
a) Time period(s)	☐ Pre-European C	ontact
	🔲 Archaic	
	Woodland I Woodland II	
	1600-1750 ± Contact Perio 1630-1730 ± Exploration at	
ğ	1730-1770± Intensified and	d Durable Occupation
		on and Early Urbanization
		and Early Suburbanization ion and Early Ex-urbanization
b) Geographical zone	Pledmont	
		ninsula ninsula/Cypress Swamp
	☐ Coastal ☐ Urban (Cit	ty of Wilmington)
c) Historic period theme		,,
o, matoric period tricin		Tanana datian and Gamana indi
	Agriculture Forestry	<ul> <li>☐ Transportation and Communication</li> <li>☐ Settlement Patterns and Demographic Changes</li> </ul>
	Trapping/Hunting Mining/QuarryIng	<ul> <li>☐ Architecture, Engineering and Decorative Arts</li> <li>☐ Government</li> </ul>
	Fishing/Oystering Manufacturing	Religion Education
Ä	Retailing/Wholesaling	Community Organizations
	Finance Professional Services	<ul><li>☐ Occupational Organizations</li><li>☐ Major Families, Individuals and Events</li></ul>

9. OTHER NOTES OR OBSERVATIONS:

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS#	N-14148	
------	---------	--

1.	ADDRESS/LOCATION: 1527 Church Road					
2.	FUNCTION(S): historic Single family dwelling current Single family dwelling					
3.	YEAR BUILT: 1952 CIRCA?: ARCHITECT/BUILDER:	_				
4.	STYLE OR FLOOR PLAN: Mid-20th century vernacular with Colonial Revival elements					
5.	INTEGRITY: original site ⊠ moved □  if moved, from whereother location's CRS #	<u>year</u>				
	list major alterations and additions with years (if known)  a.  b.	<u>year</u> 				
6.	CURRENT CONDITION: excellent  good  fair poor					
<ol> <li>DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)</li> </ol>						
	<ul> <li>a. Overall shape: Rectangular with dependencies — Stories: 2 1/2</li> <li>Additions: North side: 1-story, 2-bay with a side gable roof; South side: 1-story, 2-bay porch gable end roof; Rear: 1-story, 1-bay with a shed roof</li> </ul>	with a				
	b Structural system (if known): Balloon frame					
	с. Foundation: materials: Poured concrete basement: full 🔀 partial 🗌 not visible 🗍 по basement 🗌					
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding					
	e. Roof: shape: Side gable (steep) materials: Asphalt shingle cornice: Open dormers: None chimney: location(s): Exterior concrete block; south side					
8.	DESCRIPTION OF ELEVATIONS:					
	<ul> <li>a. Facade: Direction: W</li> <li>1) Bays 3</li> <li>2) Windows 1 on first story, 3 on second story fenestration First: unbalanced; Second: regular type 1/1 double-hung wood sash; 3-part picture window with fixed center li 1/1 double-hung sidelights (not original to house) trim None shutters Fixed, decorative vinyl</li> </ul>	ght and				

Facade (cont'd) Door(s) 1 ocation North end Wood paneled - does not appear to be original type Shallow pilasters supporting a Colonial Revival style entablature and broken trim pediment Porch(es) 4) Brick stoop b. Side: Direction: S 1) Bays 2) Windows: 1 on first story, 2 on second story; 4 on addition fenestration Regular type 1/1 double-hung wood sash trim None Fixed decorative vinyl shutters 3) Door(s) West end of elevation location type Wood paneled with multiple light fixed sash upper half trim 4) Porch(es) 1-story, 1-bay screened porch with vinyl walls and a side gable roof C. Side: Direction: N 1) Bays 2 2) Windows 1 on first story, 2 on second story fenestration Regular type 1/1 double-hung wood sash trim None shutters None 3) Door(s) None location N/A N/A type trim N/A Porch(es) 4) 1-story, 1-bay side gable addition d. Rear: Direction: E Bays 1) 3 3 on first story; 2 on second story. 2) Windows fenestration Symmetrical, but no windows in northernmost bay 1/1 double-hung wood sash type None trim shutters None 3) Door(s) On south side of 1-bay, 1-story addition location type Not visible None trim Porch(es) 1-bay, 1-story addition with vinyl siding and a shed roof 4)

- 9. INTERIOR: Not accessible
- LANDSCAPING: Set back slightly from the road; view of house obscured by large trees
- 11. OTHER COMMENTS: Construction date from tax assessment records



# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

1,	ADDRESS/LOCATION: 1527 Church Road	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1950 CIRCA?: X ARCHITECT/BUILDER: Unknown	
4,	STYLE/FLOOR PLAN:T-shaped 1-story	
5.	!NTEGRITY: original site ⊠ moved ☐  if moved, from where original location's CRS #	<u>year</u>
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent  good  fair	poor [
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1	
	c. Wall coverings Concrete block	
	d. Foundation Concrete block	
	e. Roof structural system Frame coverings Asphalt shingles openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: direction: S</li> <li>1) bays: 2</li> <li>2) windows: 1 - squared, single light fixed sash</li> </ul>	
	3) door(s): Double solid wood garage doors	
	4) other: N/A	

			CRS#	N-14148
	b.	Side: direction: E		
		1) bays: 1 2) windows: None		
		2) desertate Nessa		
		3) door(s): None		
		4) other: N/A		
	Ç,	Side: direction: N		
		1) bays: 2		
		2) windows: Not visible		
		3) door(s): Not visible		
		4) other: Not visible		
	d.	Rear: direction: W		
		1) bays: 1		
		2) windows: Not visible		
		3) door(s): Not visible		
		4) other: N/A		
9.	INTER	RIOR (if accessible):		
	a) Flo	or plan Not accessible		
	0,110	or plant		
	b) Par	rtition/walls Not accessible		
	, · <b>-</b>			
	c) Fin	ishes Not accessible		

Not accessible

d) Furnishings/machinery



# CULTURAL RESOURCE SURVEY MAP FORM

CRS#	N-14148
------	---------

1.	ADDRESS/LOCATION:	_1527 Church Road		
----	-------------------	-------------------	--	--


2. NOT FOR PUBLICATION reason:

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN NOT TO SCALE GARAGE ALLEY Ļυ<sup>₩</sup> HOUSE **H**OOOR **₩-200** CHIMNEY CHURCH ROAD N-14148

## **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

# PHOTOGRAPHIC INVENTORY

CRS#	N-14148	Date _9/2003	Photo Roll #	C-4537_ Surveyor	Gerald Kuncio
Descripti facing <u>N</u>		nd south side, fa 	cing NE; 2 - Rear	and south side, facing	NW; 3 - Garage,
Negative	location (if other	r than SHPO)			
-Attach co	ontact print(s):				
-					

doc # 20-06-01-05-12

**CRS-13** 

		-
		_
		_
		-
		-
		-
		_
		~
		-
		_
		-
		-
		_
		_
		-
		~
		_
		_

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

1.	ADDRESS/LOCATION: 1534 Church Road
2.	FUNCTION(S): historic Farmhouse current Single family dwelling
3.	YEAR BUILT: 1860 CIRCA?:   ARCHITECT/BUILDER:
4.	STYLE OR FLOOR PLAN:L-shaped mid-19th_century vernacular
5.	INTEGRITY: original site ☑ moved ☐  if moved, from where other location's CRS # year
	list major alterations and additions with years (if known)  a. Vinyl siding; removal of center gable with bargeboard detailing  b.
6.	CURRENT CONDITION: excellent  good  fair poor
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	a. Overall shape: L-shaped Stories: 2 Additions: 1-Story, partial width rear addition
	b Structural system (if known): Frame
	c. Foundation: materials: Not visible - previous CRS form says "rock" basement: full ☐ partial ☐ not visible ☒ no basement ☐
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding
	e. Roof: shape: Side gable with gable end over ell materials: Asphalt shingle cornice: Box gutters and modest gable returns dormers: None chimney: location(s): Exterior covered with vinyl; south side
8.	DESCRIPTION OF ELEVATIONS:
	<ul> <li>a. Facade: Direction: E</li> <li>1) Bays 3</li> <li>2) Windows 3 on first story, 3 on second story         fenestration Symmetrical         type First story - 1/1 paired double-hung wood sash; 2 light vertical sash window.         Second story: 1/1 double-hung wood sash         trim Plain vinyl frames         shutters None</li> </ul>

Facade (cont'd) 3) Ь. 1) 2) 3) 4) 2) 3)

Door(s) 1 location

Centered

type Wood with raised panels and 1 fixed light

trlm Plain vinyl frame

4) Porch(es) 1-Story, full-width with poured concrete floor, bedpost railings, and shed roof

Side: Direction: S

Bays 1 plus 1-story rear addition

Windows 1 in rear addition

fenestration Regular

type Vertical easement window

trim Plain vinyl frames

shutters N/A None Door(s) N/A location type N/A trim N/A

Porch(es) None

Side: Direction: N

Bays 1 plus 1 bay ell addition 1)

2 on each floor Windows

fenestration Irregular

3- 1/1 double-hung wood sash; 1-vertical casement window type

trim Vinyl frames

shutters None None Door(s) location N/A

N/A type trim N/A

4) Porch(es) None

Rear: Direction: W

1) Bays 3

2) Windows Not visible fenestration Not visible type Not visible trim Not visible shutters Not visible

3) Door(s) Not visible location Not visible type Not visible trim Not visible

4) Porch(es) Not visible

9. INTERIOR: Not accessible

LANDSCAPING: Set near the road; barn is to north; late 20th century house with large landscaped yard is also located to the south

11. OTHER COMMENTS: Date of construction from historic mapping; the house lacks integrity



# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

1.	ADDRESS/LOCATION: 1534 Church Road
2.	FUNCTION(S): historic Barn current Storage
3,	YEAR BUILT: 1860 CIRCA?: X ARCHITECT/BUILDER: Unknown
4.	STYLE/FLOOR PLAN: Rectangular
5.	INTEGRITY: original site 🖂 moved 🗌
	if moved, from where original location's CRS# year
	list major alterations and additions with years (if known)  a. b.
6.	CURRENT CONDITION: excellent  good  fair  poor
7.	DESCRIPTION:
	a. Structural system Timber frame
	b. Number of stories 1 and 2
	c. Wall coverings Barn siding; replacement siding on a portion of the east and all of the south side
	d. Foundation Stone piers and concrete sills - indicate it may have been moved to the site
	e. Roof structural system Frame coverings Metal openings None
8.	DESCRIPTION OF ELEVATIONS:
	a. Facade: direction: E 1) bays: 4 2) windows: None
	3) door(s): 3 - Original door is centered; to its south are 2 recently added barn doors; the third door is for the hayloft
	4) other: Door hardware on the original door has been replaced and is not historic

		<del></del>
	b.	Side: direction: N
		2) windows: None
		·
		3) door(s): None
		45 - Abres 5/76
		4) other: N/A
	c.	Side: direction: S
		2) windows: None
		3) door(s): None
		Ab add an Name state a
		4) other: New siding
	d.	Rear: direction: W
		1) bays: 4
		2) windows: Not visible
		,
		3) door(s): Not visible
		AN THE THE ANY A
		4) other: N/A
9.	INTER	RIOR (if accessible):
	a) Fic	por plan Not accessible
	•	•
	b) Pa	rtition/walls Not accessible
	,	
	c) Fin	nishes Not accessible
	-,	
	d) Fu	rnishings/machinery Not accessible
	2, 1 4	

# CULTURAL RESOURCE SURVEY MAP FORM

CRS#

N-5065


1.	ADDRESS/LOCATION:	1534 Church Road	
2.	NOT FOR PUBLICATION	I	

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

### INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN NOT TO SCALE BARN TOOUR  $\vdash$ W WINDOW 4 HOUSE ۱-W CHIMNEY T  $\frac{0}{1}$  $\nabla T$ 

N-5065

CHURCH ROAD

doc # 20-01-00-05-02

# DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

# CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS#	N-5065	
------	--------	--

**crs-10** 

1.	HISTORIC NAME/FUNCTION: _A	g Cx/Rhoo	des House (B	eers)-Rec	d Lion M	ethodist Ch	nu <u>rc</u> h Par	son <u>age</u>	
2.	ADDRESS/LOCATION: _1534 Chi	urch Road	l (West Side)		<u> </u>				
3.	CURRENT CONDITION: excelle	ent 🗀	good 🗵	fair		poor [		demolished	
	NITEODITY November 2				::: <b>.</b>				
4.	INTEGRITY: Vinyl siding added; ce	ntrai gaoi	e with bargeb	paro deta	iling nas	been rem	oved		
5.	SETTING INTEGRITY: Late 20th ce with the property are no longer extan		se located to	the imme	diate ea	st; farmlan	ds histori	cally associa	ted
6. F	ORMS ADDED (give number of for	ns compi	eted for eac	h):					
	#; Form:		List prop	erty type	s:				
	1 CRS 2 Main Building Form		Dwelling		<u></u>			-	
	1 CRS 3 Secondary Building	Form —	Barn						
	0 CRS 4 Archaeological Site i								
	0 CRS 5 Structure (Building-L		<u> </u>						
		ur <del>u</del> ) Fom	<u> </u>						
	0 CRS 7 Object Form						——		
	0 CRS 8 Landscape Elements	Form_							
	1 CRS 9 Map Form		<u>N/A</u>						
	0 CRS 14 Potential District Fo	rm	<u> </u>						
7.	SURVEYOR INFORMATION:								
	Surveyor name:	_Gerald	M. Kuncio						_
	Principal Investigator name:	Gerald	M. Kuncio			_			
	Principal Investigator signature:								
	Organization:	Skelly a	and Loy, Inc.		_		_ Date:	9/2/2003	<u>_</u>

**USE BLACK INK ONLY** 

<ol> <li>STATE HISTORIC CONT plan(s)):</li> <li>a) Time period(s)</li> </ol>	EXT FRAMEWORK (check all appropriate  Pre-European Contact Paleo-Indian Archaic Woodland I Woodland II	∍ boxes; refer to state management
	1600-1750± Contact Period (Native Ame 1630-1730± Exploration and Frontier Se 1730-1770± Intensified and Durable Occ 1770-1830± Early Industrialization 1830-1880± Industrialization and Early U 1880-1940± Urbanization and Early Sub 1940-1960± Suburbanization and Early	ottlement cupation Urbanization urbanization
b) Geographical zone	☐ Piedmont ☐ Upper Peninsula ☐ Lower Peninsula/Cypre ☐ Coastal ☐ Urban (City of Wilmingt	-
c) Historic period them	Agriculture	ı
	USE BLACK INK ONLY	crs-10

CRS# N-5065

8. OTHER NOTES OR OBSERVATIONS:

# DELAWARE STATE HISTORIC PRESERVATION OFFICE

## PHOTOGRAPHIC INVENTORY

CRS#	N-5065	_ Date	9/2003	_ Photo Roll #	<u>C-4537</u>	Surveyor	Gerald Kuncio
	tion 7 - Facade a and south side, f			•		-	sing SW; 9 - Barn,
Negative	e location (if othe	er than S	HPO)				
Attach c	contact print(s):						
		-11			_ <b>_</b>		1







doc # 20-06-01-05-12

**CRS-13** 

		-
		_
		_
		_
		_
		-
		-
		_
		_
		_
		~
		_
		_
		_
		_
		_
		_
		_

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

 CRS #
 N-14149

 SPO Map
 06.07.32

 Hundred
 New Castle

 Quad
 St. Georges

 Other
 10-053-00002

1.	HISTORIC NAME/FUNCTION:	Owelling, 1531 Church Road					
		, , , , , , , , , , , , , , , , , , ,					
2.	ADDRESS/LOCATION: 1531 Church Road (East Side)						
3.	TOWN/NEAREST TOWN: Bear		vicinity? 🖂				
4.	MAIN TYPE OF RESOURCE:	building 🔀 structure 🗌 site	e 🗌 object 🗌				
5.	MAIN FUNCTION OF PROPERTY:	Dwelling					
6.	PROJECT TITLE/ REASON FOR S Church Road (Wynnefield to S.R.						
7. /	ADDITIONAL FORMS USED:						
	#; Form:	List property types:					
	1 CRS 2 Main Building Form						
	1 CRS 3 Secondary Building						
	0 CRS 4 Archaeological Site						
	0 CRS 5 Structure (Building-						
	0 CRS 6 Structure (Land Fea						
	0 CRS 7 Object Form						
	0 CRS 8 Landscape Element	s Form					
	1 CRS 9 Map Form	N/A					
	0 CR\$ 14 Potential District F	orm					
8. 3	SURVEYOR INFORMATION:						
	Surveyor name:	Gerald M. Kuncio					
	Principal Investigator name:	Gerald M, Kuncio					
	Principal Investigator signature:						
	Organization:	Skelly and Loy, Inc.	Date: 9/2/2003				

Dwelling constructed di	iring the post-World War II	era	
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check	all appropriate boxes; refer to state mana	gement
a) Time period(s)	☐ Pre-European Co ☐ Paleo-Indian ☐ Archaic ☐ Woodland I ☐ Woodland II	ontact	
	1600-1750 ± Contact Period 1630-1730 ± Exploration ar 1730-1770 + Intensified and 1770-1830 ± Early Industria	nd Frontier Settlement d Durable Occupation alization	
		on and Early Urbanization and Early Suburbanization on and Early Ex-urbanization	
b) Geographical zone	Coastal		
c) Historic period theme	i(e)		
	Agriculture Forestry Trapping/Hunting Mining/Quarrying FishIng/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	<ul> <li>□ Transportation and Communication</li> <li>☑ Settlement Patterns and Demograph</li> <li>□ Architecture, Engineering and Decor</li> <li>□ Government</li> <li>□ Religion</li> <li>□ Education</li> <li>□ Community Organizations</li> <li>□ Occupational Organizations</li> <li>□ Major Families, Individuals and Even</li> </ul>	ative Arts
	USE BLACK	INK ONLY	crs-1

CRS# N-14149

9. OTHER NOTES OR OBSERVATIONS:



# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

1.	ADDRESS/LOCATION: 1531 Church Road	
2.	FUNCTION(S): historic <u>Dwelling</u> <u>current Dwelling</u>	
3.	YEAR BUILT: 1948 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE OR FLOOR PLAN: Mid-20th century vernacular	
5.	INTEGRITY: original site 🗵 moved 🔲	
	if moved, from where other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known)	year
	a	
6.	CURRENT CONDITION: excellent  good  fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leaveleanks.)	e no
	a. Overall shape: Rectangular Stories: 1 1/2 Additions: None	
	b Structural system (if known): Timber frame	
	c. Foundation: materials: Not visible basement: full ⊠ partial □ not visible □ no basement □	
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding	
	e. Roof: shape: Cross gable materials: Asphalt shingle cornice: Open dormers: None chimney: focation(s): Brick exterior; south side	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: Direction: W</li> <li>1) Bays 2</li> <li>2) Windows 2         fenestration Balanced         type 1/1 wood sash and tri-partite picture window with center fixed light an         wood sash side lights         trim None         shutters None</li> </ul>	d 1/1

Facade (cont'd) Door(s) None 3) N/A location N/A type N/A trim Porch(es) None 4) Side: Direction: S b. 3 1) Bays 2) Windows 2 fenestration Regular 1/1 wood sash type None trim shutters None 3) Door(s) location West end of elevation Solid wood with raised panels type trim None 4} None Porch(es) Side: Direction: N 3 1) Bays 2) Windows 3 fenestration Regular 1/1 double-hung wood sash type None trim None shutters None 3} Door(s) location N/A N/A type N/A trim None 4) Porch(es) d. Rear: Direction: E 2 1) Ваув 2) Windows 2 fenestration Regular 1/1 double-hung wood sash type trlm None None shutters 3) Door(s) Slightly off center to the south location type Wood with six fixed lights trim None None 4) Porch(es)

- 9. INTERIOR: Not accessible
- 10. LANDSCAPING: Set back slightly from the road; to the south is a parking lot for the Red Lion Church
- 11. OTHER COMMENTS: Construction date from tax assessment records

# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

1.	ADDRESS/LOCATION: 1531 Church Road	_
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: 1948 CIRCA?: ⊠ ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: Rectangular	
5.	INTEGRITY: origiπal site 🗵 moved 🗌	
	if moved, from where original location's CRS #	year
	list major alterations and additions with years (if known) a. b.	year —
6.	CURRENT CONDITION: excellent ⊠ good ☐ fair ☐ p	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1	
	c. Wall coverings Concrete block	
	d. Foundation Concrete block	
	e. Roof structural system Frame coverings Asphalt shingle openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul><li>a. Facade: direction: S</li><li>1) bays: 1</li><li>2) windows: None</li></ul>	
	3) door(s): 1 fiberglass automobile door	
	4) other: NA	

CRS#	N14149	
------	--------	--

- b. Side: direction: E
  - 1) bays: 1
  - 2) windows: 1 with four louvered lights
  - 3) door(s): None
  - 4) other: NA
- c. Side: direction: W
  - 1) bays: 1
  - 2) windows: 1 with four louvered lights
  - 3) door(s): None
  - 4) other: NA
- d. Rear: direction: N
  - 1) bays: 1
  - 2) windows: Not visible
  - 3) door(s): Not visible
  - 4) other: N/A
- 9. INTERIOR (if accessible):
  - a) Floor plan

Not accessible

b) Partition/walls Not accessible

c) Finishes

Not accessible

d) Furnishings/machinery

Not accessible

## **CULTURAL RESOURCE SURVEY** MAP FORM

N-14149 CRS#


1.	ADDRESS/LOCATION:	1531 Church Road	

NOT FOR PUBLICATION 2. reason:

3. **LOCATION MAP:** 

> Indicate position of resource in relation to geographical landmarks such as streams and crossroads. (attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN NOT TO SCALE PARKING LOT GARAGE |-DOOR W WЦ HOUSE ŀΨ  $W\dashv$ CHIMNEY  $\vdash W$ WΗ DRIVEWAY  $\overline{\mathbb{A}}$  $\overline{V}$ N D O CHURCH ROAD N-14149

# **DELAWARE STATE HISTORIC PRESERVATION OFFICE**

# PHOTOGRAPHIC INVENTORY

CRS#	N-14149	Date	9/2003_	_ Photo Roll #	C-4537	Surveyor	Gerald Kuncio
Descript facing N	tion 4 - Facade IW	and nort	h side. faci .—	ng SE; 5 -South	side and r	ear, facing l	NW; 6 - Garage
Negative	e location (if oth	er than S	HPO) _				
Attach c	ontact print(s):						



doc # 20-06-01-05-12

**CRS-13** 

			_
			_
			_
			_
			_
			_
			-
			-
			-
			_
			-
			_
			_
			_
			_
			_
			_
_		<del>-</del>	

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-14150
SPO Map	06.07.32
Hundred	New Castle
Quad	St. Georges
Other	10-053-00003

1.	HISTORIC NAME/FUNCTION:	Red Lion Methodist Church Social	<u>H</u> all		
2.	ADDRESS/LOCATION: East si	de of Church Road, north of the R	ed Lion Me	thodist Chu	<u>rc</u> h
3.	TOWN/NEAREST TOWN: Bear				vicinity? 🖂
4.	MAIN TYPE OF RESOURCE:	building ⊠ structure landscape ☐ distric		site 🗌	object [
5.	MAIN FUNCTION OF PROPERTY	': Social Hall			
6.	PROJECT TITLE/ REASON FOR Church Road (Wynnefield to S.R.				
7.	ADDITIONAL FORMS USED:				
	#: Form:	List property types:			
	1 CRS 2 Main Building Form				_
	0 CRS 3 Secondary Building Form				
	0 CRS 4 Archaeological Site				
	0 CRS 5 Structure (Building				
	0 CRS 6 Structure (Land Fe		_		
	0 CRS 7 Object Form	· — —			
	0 CRS 8 Landscape Elemen	ts Form			
	1 CRS 9 Map Form	N/A			
	0 CRS 14 Potential District I	<u> </u>			
8.	SURVEYOR INFORMATION:				
	Surveyor name:	Gerald M. Kuncio			
	Principal Investigator name:	Gerald M. <u>Kunci</u> o			
	Principal Investigator signature:				
	Organization:	Skelly and Loy, Inc.		Date:	9/2/2003

Dwelling constructed ca. 1940, according to a history of the Red Lion Methodist Church			
10. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (check all appropriate boxes; refer to state management		
a) Time period(s)	☐ Pre-Europea⊓ Contact ☐ Paleo-Indian		
	☐ Archaic ☐ Woodiand I		
	Woodland II		
	1600-1750± Contact Period (Native American) 1630-1730± Exploration and Frontier Settlement		
Ä	1730-1770 - Intensified and Durable Occupation 1770-1830 - Early Industrialization		
	1830-1880± Industrialization and Early Urbanization 1880-1940± Urbanization and Early Suburbanization 1940-1960± Suburbanization and Early Ex-urbanization		
h) Ca	·		
b) Geographical zone	☐ Pledmont ☐ Upper Peninsula		
	Lower Peninsula/Cypress Swamp Coastal		
a) 1854	☐ Urban (City of Wilmington)		
c) Historic period theme			
	Agriculture		
	Trapping/Hunting Architecture, Engineering and Decorative Arts  Mining/Quarrying Government		
	Fishing/OysterIng		
	Retailing/Wholesaling		
Ц	Professional Services Major Families, Indíviduals and Events		

9. OTHER NOTES OR OBSERVATIONS:

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-14150

1.	ADDRESS/LOCATION: East side of Church Road, north of Red Lion Methodist Church	
2.	FUNCTION(S): historic Social Hall current Social Hall	
3.	YEAR BUILT: 1940 CIRCA?:   ARCHITECT/BUILDER:	
4.	STYLE OR FLOOR PLAN: Mid-20th century social/commercial vernacular architecture	
<b>5</b> .	INTEGRITY: original site 🖂 moved 🔲	
	if moved, from where other location's CRS #	<u>year</u>
	list major alterations and additions with years (if known)  a. Paneling, carpeting, and drop ceiling on first floor interior; paneling and offices, second floor  b. Concrete block kitchen addition to the rear	y <del>e</del> ar
6.	CURRENT CONDITION: excellent  good  fair poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave blanks.)	• no
	a. Overall shape: Rectangular Stories: 2 Additions: 1-Story concrete block addition to the rear	
	b Structural system (if known): Heavy frame (source: custodian)	
	c. Foundation: materials: Poured concrete basement: full ☐ partial ☐ not visible ☐ no basement ☒	
	<ul> <li>d. Exterior walls (original if visible&amp; any subsequent coverings): Asbestos siding over wide woo planks</li> </ul>	d
	e. Roof: shape: Pyramidal materials: Asphalt shingle cornice: Box gutters dormers: None chimney: location(s): 2 exterior brick chimneys; north side and rear	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: Direction: W</li> <li>1) Bays 3</li> <li>2) Windows First story: 2; Second story: 3 fenestrationRegular type 1/1 vinyl sash trim None shutters None</li> </ul>	

Facade (cont'd) Door(s) location Centered Metal with 6 raised panels type trim Plain wood frame 4) Porch(es) 1-bay, half-hipped awning sheltering door Side: Direction: N b. 1) **Bays** 2) Windows First story: 3; Second story: 2 fenestration Regular 1/1 vinyl sash type trim None shutters None 31 Door(s) location Second story, rear Metal with nine fixed lights at the top type Simple wood frame trim 4) Porch(es) Wood fire stairs and landing Side: Direction: S C. 1) **Bavs** 2) Windows 4 on each story fenestration Regular 1/1 vinyl sash type trim None None shutters 3) Door(s) First story, rear location Metal with 1 fixed light type Plain wood frame trim 4) Porch(es) Cantilevered half-hipped awning sheltering the door Rear: Direction: E d. Bays 1) 2) Windows 2 on second story fenestration Regular 1/1 vinyl sash type trim None shutters None 3) Door(s) First story, south side - now permanently closed, as used as vent for kitchen location equipment type Metal trim None 4) Porch(es) None - there is a 1-story, 2-bay concrete block addition wth a shed roof, 1/1

- 9. INTERIOR: First floor: open floor plan with metal columns running down center; imitation wood paneling, newer carpeting, and drop ceiling; at rear, in concrete block portion, is a kitchen. Second floor: originally an open room with a stage, it has been converted into a warren of offices and classrooms.
- 10. LANDSCAPING: Set near the road, north and across a section of the parking lot from the Red Lion Methodist Church

wood sash windows, and a shed roof


11. OTHER COMMENTS: Date of construction provided by a history of the Red Lion Methodist Church; building has lost integrity.

#### **CULTURAL RESOURCE SURVEY** MAP FORM

CRS#	N-14150
------	---------


1.	ADDRESS/LOCATION: East side of Church Road, North of Red Lion Methodist Church
2.	NOT FOR PUBLICATION    reason:
3.	LOCATION MAP:
	Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
	(attach section of USGS quad map with location marked or draw location map )

#### INDICATE NORTH ON SKETCH



CRS-9

#### INDICATE NORTH ON PLAN




#### PHOTOGRAPHIC INVENTORY

CRS # N-14150 Date 9/2003 Photo Roll # C-4538 Surveyor Gerald Kuncio

Description 9 - Facade and north side, facing SE; 14 - Interior of first floor from front to rear, facing E; 15 - Interior of first floor from front to rear, facing NE; 16 -Interior of first floor from front to rear, facing NE; 17 - Interior of second floor from front to rear, facing E

Negative location (if other than SHPO)

Attach contact print(s):



doc # 20-06-01-05-12

#### DELAWARE STATE HISTORIC PRESERVATION OFFICE

#### PHOTOGRAPHIC INVENTORY

CRS#	N- <u>14150</u>	Date	9/2003	Photo Roll#	C-45 <u>37</u>	Surveyor	Gerald Kuncio
_Description 11 - South side and rear, facing NW; 13 - South side and rear, facing NW; 24 - Facade and north side, facing SE							
Negative location (if other than SHPO)							
Attach d	contact print(s):						



		-
		_
		~
		-
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		<b>-</b> .
		_

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-498

	THE PROPERTY OF THE PROPERTY O							
1.	ADDRESS/LOCATION: 1545 Church Road							
2.	FUNCTION(S): historic Church current Church							
3.	YEAR BUILT: 1853 CIRCA?:  ARCHITECT/BUILDER:							
4.	STYLE OR FLOOR PLAN: Original: rectangular; Current: L-shaped							
5.	INTEGRITY: original site 🖂 moved 🗌							
	if moved, from where other location's CRS #	<u>year</u>						
	list major alterations and additions with years (if known)  a. Additions to south side and rear  b. New carpeting and pews in santuary	<u>year</u> 1959 1969						
_		1909						
6.	CURRENT CONDITION: excellent  good  fair  poor							
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)							
	<ul> <li>a. Overall shape: L-shaped Stories: 3</li> <li>Additions: 1-Story, 4-bay by 3-bay with side gable roof on the south side; 2-story, 3-bay additions on the church; 2-story, 1-bay extension on the north side; church entrance on facade</li> </ul>							
	b Structural system (if known): Brick							
	c. Foundation: materials: Brick basement: full partial not visible no basement 🔀							
	d. Exterior walls (original if visible& any subsequent coverings): Brick							
	e. Roof: shape: Pediment materials: Asphalt shingle cornice: Box gutters dormers: None chimney: location(s): Brick exterior; rear							
8.	DESCRIPTION OF ELEVATIONS:							
	a. Facade: Direction: W 1) Bays 3 2) Windows 2 on each story fenestration Symmetrical type First story: 5/6 vinyl sash with applied muntins; Second and third story stained glass trim Brick sills shutters Fixed, decorative vinyl on first story	ories:						

CRS# N-498 Facade (cont'd) 3) Door(s) location Centered Double wood doors with multiple lights, sidelights, and transom under a type pediment roof - not original to the church Sidelights and transom trim 1-story, 1-bay with pediment roof; not original to the church Porch(es) 4) b. Side: Direction: S Bays Original: 5; Current: 8 1) 2) Windows 4 on each story fenestration Symmetrical First story: 6/6 vinyl sash with applied muntins; Second and third stories: type stained glass Brick sills trim shutters None None 3) Door(s) N/A location N/A type N/A trim 4} Porch(es) None Side: Direction: N Bavs Original: 5; Current: 8 1) 2) Windows 4 on each story fenestration Symmetrical First story: 6/6 vinyl sash with applied muntins; Second and third stories: type stained glass trim **Brick sills** None shutters 3) Door(s) location Within 1-story, 1-bay addition Double metal and glass doors type trim None Sheltered entrance 4) Porch(es) d. Rear: Direction: E Original: 3; Current: 7, counting 1959 addition 1) Bays 2) First story: 4; Second and third stories: 2 Windows fenestration Unbalanced First: 8/8 vinyl sash with applied muntins; Second and third: stained glass type **Brick sllls** trim None shutters 3) Door(s) None N/A location

- INTERIOR: Extensively altered. Sanctuary was expanded and completely redone in the 1950s and 1960s, 9. with new pews, carpet, and lighting installed, and the balcony expanded. The first floor is similarly altered for use as offices and classrooms. In short, little interior fabric remains.
- LANDSCAPING: Set near road with narrow, landscaped front lawn, parking lots to the north and rear, and an open field to the south
- 11. OTHER COMMENTS: Facade and north and south sides have pilasters with corbeled tops

N/A

N/A

type trim

Porch(es)

4)

# CULTURAL RESOURCE SURVEY MAP FORM

CRS # N-498

1.	ADDRESS/LOCATION:	1545 Church Road


2. NOT FOR PUBLICATION reason:

#### 3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

#### INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN NOT TO SCALE CHIMNEY ¥ ΗW ΗD ⊬W W TO O O R  $\overline{\mathbf{W}}$  ${\overline{\overline{W}}}$  $\overset{\top}{W}$ ŀΨ PARKING LOT ₩ij ŀ₩ W⊢ ⊢W ₩H ⊬W WΗ **HWINDOW** WΗ T. CHURCH ROAD N 498

doc # 20-01-00-05-02

## DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

## **CULTURAL RESOURCE SURVEY** SURVEY UPDATE FORM

CRS#	N-498	

1. HISTORIC NAME/FUNCTION	ON: Red Lion United Methodist Church/Let	oanon Methodist Church
. ADDRESS/LOCATION:	1545 Church Road (East Side)	
. CURRENT CONDITION:	excellent 🗌 good 🖂 fair 🗀	] poor
	y by 3-bay addition south side; addition to rea ance; complete remodeling of the sanctuary a	
s. <b>SETTING INTEGRITY</b> : Par	rking lot to north and behind; late 20th century	house across Church Road
	er of forms completed for each}:	
#: Form:	List property types:	
1 CRS 2 Main Buildin		
0 CRS 3 Secondary E		
0 CRS 4 Archaeologi		
0 CRS 5 Structure (B		
0 CRS 6 Structure (L		
0 CRS 7 Object Form		
0 CRS 8 Landscape E	Elements Form	
1 CRS 9 Map Form	N/A	
0 CRS 14 Potential D	istrict Form	
7. SURVEYOR INFORMATIO	N:	
Surveyor name:	_Gerald M. Kunc <u>i</u> o	
Principal Investigator nam	ne: Gerald M. Kuncio	
Principal Investigator sign	nature:	
Organization:	Skelly and Loy, Inc.	Date: _9/2/2003
loc # 20-01-00-05-02	USE BLACK INK ONLY	crs-10

USE BLACK INK ONLY

Extensive interior and e	exterior alterations compr	omise integrity	
9. STATE HISTORIC CONT plan(s)):	EXT FRAMEWORK (chec	k all appropriate boxes; refer to state manage	ement
a) Time period(s)	☐ Pre-European ☐ Paleo-Indian	Contact	
	Archaic Woodland I		
	☐ Woodland il		
	1600-1750		
	1730-1770± Intensified a 1770-1830+ Early Indust	ind Durable Occupation	
×	1830-1880 - Industrializa	ntion and Early Urbanization n and Early Suburbanization	
		ation and Early Ex-urbanization	
b) Geographical zone	☐ Piedmoi		
	Lower P	eninsula eninsula/Cypress Swamp	
	☐ Coastal ☐ Urban (C	City of Wilmington)	
c) Historic period them	e(s)		
	Agriculture	Transportation and Communication	
	Forestry Trapping/Hunting	<ul> <li>Settlement Patterns and Demographic</li> <li>Architecture, Engineering and Decora</li> </ul>	
	Mining/Quarrying Fishing/Oystering	☐ Governmeπt ☑ Religion	
	Manufacturing Retailing/Wholesaling	☐ Education ☐ Community Organizations	
Ä	Finance Professional Services	Occupational Organizations Major Families, Individuals and Event	9
		in major i minimos; marriadalo and Event	
	USE BLAC	CK INK ONLY	crs-10

**USE BLACK INK ONLY** 

CRS# N-498

8. OTHER NOTES OR OBSERVATIONS:


#### PHOTOGRAPHIC INVENTORY

-CRS # N-498 \_\_\_\_ Date 9/2003 Photo Rolf # C-4538 Surveyor Gerald Kuncio

Description 1 -Interior of the sanctuary from the rear, facing E; 2 - Interior of the sanctuary from the rear, facing E; 3 - Interior of the sanctuary from the southeast corner, facing NW; 4 - Interior of the sanctuary from the altar, facing W; 5 - Interior of the sanctuary from the choir loft, facing E; 6 - Interior of the sanctuary from the choir loft, facing E; 7 - Interior of the first floor from the entrance, facing E; 8 - Interior of the first floor from the entrance, facing E

Negative location (if other than SHPO).





#### DELAWARE STATE HISTORIC PRESERVATION OFFICE

#### PHOTOGRAPHIC INVENTORY

CRS # N-498 Date 9/2003 Photo Roll # C-4537 Surveyor Gerald Kuncio

Description 12 - Rear and portion of north side, facing SW; 14 - North side showing original and added construction, facing SE; 15 - Facade and north side, facing SE; 16 - Facade, south side, and 1959 addition, facing E; 17 - 1959 addition to south side, facing NE

Negative location (if other than SHPO)

Attach contact print(s):



_
~
_
_
-
-
_
_
_
~
_
_
_
-
_
_
~
-

# CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

CRS#	N-1237
SPO Map	08-09-32
Hundred	New Castle
Quad	St. Georges
Other	10-053-00011

1.	ніст	ORIC NAME/FUNCTION:	Silver Farmhouse		
٠.	1,1011		Oliver i dilimouse	_	
2.	ADDI	RESS/LOCATION: 1554 C	hurch Road (West Side)		
3.	TOW	N/NEAREST TOWN: Bear		,	vicinity? 🔀
4.	MAIN	TYPE OF RESOURCE:	building S structure Site landscape district		object 🗀
5.	MAIN	FUNCTION OF PROPERTY	: Dwelling		
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Church Road (Wynnefield to S.R. 71) Improvements					
7	AUUIIII	ONAL FORMS USED:			
	#:	Form:	List property types:		
	1	CRS 2 Main Building Form		_	
	2	CRS 3 Secondary Building			
	0	CRS 4 Archaeological Site			
	0 CRS 5 Structure (Building-Like) Form				
	0 CRS 6 Structure (Land Feature) Form				
	0 CRS 7 Object Form				
	0	CRS 8 Landscape Elemen	ts Form		
	1	CRS 9 Map Form	N/A	-	
	0	CRS 14 Potential District I	-orm		
8.	SURVE	YOR INFORMATION:			
	Survey	or name:	Gerald M. Kuncio		_
	Princip	al Investigator name:	Gerald M. Kuncio		
	Princip	al Investigator signature:			
	Organi	zation:	Skelly and Loy, inc.	Date:	9/2/2003

10. STATE HISTORIC CONT plan(s)):	·		fer to state management
a) Time period(s)	☐ Pre-European ( ☐ Paleo-Indian ☐ Archaic ☐ Woodland I ☐ Woodland II	Contact	
	1880-1940± Urbanization	and Frontier Settlement nd Durable Occupation	n
b) Geographical zone	Coastal		
c) Historic period them	e(s)		
	Agriculture Forestry Trapping/Hunting MinIng/QuarryIng Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services		and Demographic Changes eering and Decorative Arts zations nizations
	IISE BI AC	'K INK ONLY	cps.1

CRS# N-1237

9. OTHER NOTES OR OBSERVATIONS:

# A STATE OF THE STA

doc# 20-06-01-05-02

#### DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

# CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# N-1237

crs-2

1.	ADDRESS/LOCATION: 1554 Church Road	
2.	FUNCTION(S): historic Single family dwelling current Mutiple family dwelling	
3.	YEAR BUILT: 1882 CIRCA?: ARCHITECT/BUILDER:	
4.	STYLE OR FLOOR PLAN: 19th century vernacular with a center hall plan	
5.	INTEGRITY: original site ⊠ moved ☐  if moved, from where	<u>year</u>
	list major alterations and additions with years (if known)  a. Vinyl siding, loss of bargeboard detailing, interior redesign  b.	<u>year</u>
6.	CURRENT CONDITION: excellent  good  fair  poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave blanks.)	no
	a. Overall shape: Rectangular Stories: 2 1/2 Additions: None	
	b Structural system (if known): Frame	
	c. Foundation: materials: Stone (house); stone piers (porch); brick (bay windows) basement: full ☐ partial ☒ not visible ☐ no basement ☐	
	d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding	
	e. Roof: shape: Cross gable materials: Asphalt shingle cornice: Overhanging eaves dormers: Wall dormer at the front of the house chimney: location(s): Centered at the front slope of the roof	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: Direction: S</li> <li>1) Bays 3</li> <li>2) Windows First story: 2; Second story: 3 fenestration Regular type 2/2 double-hung wood sash trim Plain wood frame shutters None</li> </ul>	

USE BLACK INK ONLY

```
Facade (cont'd)
                         2
          Door(s)
             location
                         Centered
                         Double wood paneled doors with fixed top lights and a filled transom;
             type
          contained in a 1-bay extension of the facade
                         Simple wood frame and filled transom
             trim
                         1-story, full-width with a shed roof, sawtooth trim, bedpost columns with top
     4)
          Porch(es)
          brackets, wood floor, and stone piers
    Side: Direction: E
Ь.
          Bays
     1)
          Windows
     2)
                         First story: 4 (3 in 1-story bay with a half-hipped roof); Second and third
          stories: 2 each
             fenestration Regular
                         1/1 double-hung wood sash in bay window; all others 2/2 double-hung wood
             type
          sash
                         Plain wood frames
             trim
             shutters
                         None
                         None
     3)
          Door(s)
                         N/A
             location.
                         N/A
             type
                         N/A
             trim
     4)
          Porch(es)
                         None
    Side: Direction: W
     1)
          Bays
    2)
          Windows
                         First story: 4 (3 in 1-story bay with a half-hipped roof); Second and third
          stories: 2 each
             fenestration Regular
                         1/1 double-hung wood sash in bay window; all others 2/2 double-hung wood
             type
          sash
                         Plain wood frames
             trim
                         None
             shutters
     3)
          Door(s)
                         First story rear
             location
                         Double sliding glass door
             type
                         None
             trim
          Porch(es)
                         None - But there are wood fire stairs and decks on all three stories
     4)
d.
    Rear: Direction: N
                         3
     1)
          Bays
    2)
          Windows
                         First story: 3; Second story: 2
             fenestration Symmetrical
             type
                         2/2 double-hung wood sash
             trim
                         Plain wood frames
             shutters
                         None
     3)
          Door(s)
             Jocation
                         Sheltered by the rear porches
             type
                         Raised panel with 4 fixed lights
                         Plain wood frames
             trim
     4)
          Porch(es)
                         2, 1-story each, located at the end bays. West bay: half-hipped roof with
```

9. INTERIOR: Not accessible; however, the building has been converted into three apartments, undoubtedly compromising interior integrity.

asphalt shingles, single squared wood column, wood floor. East bay: shed roof with asphalt

- 10. LANDSCAPING: Sits on a small bench and faces Red Lion Road. Total acreage: 2.16. At rear of property, separated by a driveway and parking area for the apartments, are two large storage buildings that are not original to the property.
- 11. OTHER COMMENTS: Construction date from tax assessment records

shingles, bedpost column, wood floor



# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N-1237

1.	ADDRESS/LOCATION: _1554 Church Road	
2.	FUNCTION(S): historic Barn current Storage	
3.	YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: Rectangular	
5.	INTEGRITY: original site 🗵 moved 🗌  if moved, from where original location's CRS #	<u>ү</u> еаг 
	list major alterations and additions with years (if known) a. b.	year —
6.	CURRENT CONDITION: excellent  good  fair	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Frame	
	b. Number of stories 1	
	c. Wall coverings Vertical board siding	
	d. Foundation Concrete block	
	e. Roof structural system Frame coverings Metal openings 3 Metal pipe ventilators at the ridge line	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: S	

3) door(s): 3 Doors - double barn door on extension at east end; single sliding door near the center of the

other: 2-Bay wide, 1-bay deep extension at east end; 3-bay wide extension at the center of the south

2) windows: None

side; roof has exposed rafter tails

CRS#	N-1237	

b. Side: direction: E

1) bays: 2

2) windows: None

3) door(s): None

4) other: N/A

c. Side: direction: W

1) bays: 1

2) windows: None

3) door(s): 1 - Roll-up metal garage door

4) other: N/A

d. Rear: direction: N

1) bays: 6

2) windows: None

3) door(s): 1 - Metal pedestrian door with a single fixed light

4) other: Exposed rafter tails

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



# CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS#	N-1237	

1.	ADDRESS/LOCATION: 1554 Church Road	
2.	FUNCTION(S): historic <u>Garage/storage</u> current <u>Garage/Storage</u>	
3.	YEAR BUILT: 1940 CIRCA?: X ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: Rectangular	
5.	INTEGRITY: original site  moved  original location's CRS #	year
	list major alterations and additions with years (if known) a. b.	year
6.	CURRENT CONDITION: excellent good fair	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1	
	c. Wall coverings Concrete block, vertical boards, sheet metal	
	d. Foundation Concrete block	
	e. Roof structural system Frame coverings Metal openings None`	
8.	DESCRIPTION OF ELEVATIONS:	
	<ul> <li>a. Facade: direction: S</li> <li>1) bays: 5</li> <li>2) windows: 1 - Metal sash with six lights in a sliding barn door</li> </ul>	
	3) door(s): 3 - 1 wood pedestrian door; 2 - sliding barn/warehouse doors with vertical board siding	

4) other: Wall finishes: concrete block, vertical board (on doors), and sheet metal

CRS#	N-1237	
------	--------	--

b.	1)	e: direction: W bays: 4 windows: 1 - 1/1 double-hung wood sash; a second window is boarded
	3)	door(s): 1 - Paneled wood door
	4)	other: N/A
c.	Sid 1) 2)	e: direction: E bays: 4 windows: Not visible

3) door(s): Not visible

4) other: N/A

d. Rear: direction: N

1) bays: 5

2) windows: None

3) door(s): 1 - Metal roll-up garage door

4) other: 3 Wall finishes - concrete block, vertical board, corrugated metal

#### INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible

## CULTURAL RESOURCE SURVEY MAP FORM

CRS#	N-1237
~11~ n	, , , ,


1.	ADDRESS/LOCATION:	1554 Church Road	
_	NOT FOR BURLICATION		

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

#### INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN ΤD Ч GARAGE/STORAGE Ψ NOT TO SCALE ₩, CHIMNEY T D D DН BARN DRIVEWAY W D H ρН  $\vdash W$ HOUSE CHIMNEY +000R N-1237

#### PHOTOGRAPHIC INVENTORY

CRS# N-1237

9/2003 Date

Photo Roll # C-4538

Surveyor Gerald Kuncio

Description 10 -Barn facade and east side, facing NW; 11 - Barn west side and rear, facing SE; 12 -Garage facade and west side, facing NE: 13 - Barn west side and rear, facing SE

Negative location (if other than SHPO)

\_Attach contact print(s):









doc # 20-06-01-05-12

**CRS-13** 

#### DELAWARE STATE HISTORIC PRESERVATION OFFICE

#### PHOTOGRAPHIC INVENTORY

Photo Roll # C-4537 Surveyor Gerald Kuncio CRS# N-1237 Date 9/2003

Description 18 - East side and rear, facing SW; 19 - East side and rear, facing SW; 20 - Facade and east side, facing N; 21 - West side and rear, facing SE; 22 - Outbuildings, facing NE; 23 - Barn. facade and east side, facing NW

Negative location (if other than SHPO)

Attach contact print(s):













doc # 20-06-01-05-12

**CRS-13** 

		-
		_
		-
		-
		_
		-
		-
		-
		_
		-
		_
		-
		-
		_
		-
		_
		_
		_

#### PHOTOGRAPHIC INVENTORY - CONTACT SHEET

Negative location (if other than SHPO) Photo Roll # C-4535 Surveyor Gerald M. Kuncio Date Sept. 2003 Frame # CRS# Description of view N-14133 Facade and south side, facing NW N-14133 12 Façade, facing W 13 N-14133 Barn, facing SW Portion of facade and north side, facing W N-14134 14 15 N-14134 Façade, hyphen, and garage, facing NW 16 N-14135 Facade and north side, facing SE (built 1969) N-14135 Facade and north side, facing E (built 1969) 17 18 N-14136 Facade, facing NE (built 1969) N-14136 Facade, facing E (built 1969) 19 Facade showing original portion and addition, facing E 20 N-14137 Relationship of house and garage, facing SE 21 N-14137 22 N-14137 South end, facing NE 23 N-14137 Garage and shed, facing NE 24 N-14137 Garage and shed, facing NE 25 N-14137 Detail of garage, facing NE

			-
			_
			-
			-
			_
			_
			_
			_
			-
			_
			_
			_
			_
			_
			_
			_
			_

## **PHOTOGRAPHIC INVENTORY - CONTACT SHEET**

Negative location (if other than SHPO)							
Photo Rol	l# <u>C-4536</u>	Surveyor Gerald M. Kuncio Date Sept. 2003					
Frame #	CRS#	Description of view					
2	N-14138	Facade facing E (built 1977)					
3	N-14138	Facade facing E (built 1977)					
4	N-14138	Portion of facade and south side, facing NE (built 1977)					
5	N-14138	Portion of facade and south side, facing NE (built 1977)					
6	N-14139	Facade and north side, facing SW					
7	N-14139	Facade and south side, facing NW					
8	N-14139	Shed, facing W					
9	N-14140	Facade, south side, and portion of rear, facing NW					
10	N-14140	Facade, north side, and rear ell, facing SW					
11	N-14141	Facade and south side, facing NW					
12	N-14141	Garage, facing W					
13	N-14142	Facade and north side, facing SE					
14	N-14142	Facade, south side, and garage, facing NE					
15		House built after 1960					
16		House built after 1960					
	N-14143	Facade and north side, facing SE					
18	N-14144	Facade, hyphen, and former garage, facing W					
19	N-14144	Garage and south side, facing NW					
20	N-14145	Facade and north side, facing SW					
21	N-14145	Rear and north side, facing SE					

			-
			-
			_
			_
			-
			-
			_
			_
			_
			_
			-
			-
			_
			_
			_
			_
			_
			_
			_
 	 ,		

#### PHOTOGRAPHIC INVENTORY - CONTACT SHEET

Photo Ro	II# C-4536	Surveyor <u>Gerald M. K</u> uncio	_ Date	Sept. 200 <u>3</u>
Frame #	CRS#	Description of view	_	
22	N-14146	Facade, hyphen, and garage, facin	g NW	
23	N-14147	North side showing dormers, facing	) SE	
24	N-14147	Facade and south side, facing NE		
25	N-14147	Facade and south side, facing NE		
				_
			_	
			_	
	<del></del>			_
	_			
 loc # 20-06-		USE BLACK INK ONLY	_	 CRS - 12

USE BLACK INK ONLY

doc # 20-06-01-05-11

-
-
_
-
_
_
-
_
_
_
_
~
_
_
_
~
_
-

#### PHOTOGRAPHIC INVENTORY - CONTACT SHEET

Photo Ro	II# <u>C-4</u> 537	Surveyor Gerald M. Kuncio Date Sept. 2003
Frame #	CRS#	Description of view
1	N-14148	Facade and south side, facing E
2	N-14148	Rear and south side, facing NW
3	N-14148	Garage, facing NW
4	N-14149	Facade and north side, facing SE
5	N-14149	South side and rear, facing NW
6	N-14149	Garage, facing NW
7	N-5065	Facade and south side, facing NW
8	N-5065	Facade and north side, facing SW
9	N-5065	Barn, facade and south side, facing NW
10	N-5065	Barn, facade and north side, facing SW
1 <b>1</b>	N-14150	South side and rear, facing NW
12	N-498	Rear and south additions, facing SW
13	N-14150	South side and rear, facing NW
14	N-498	North side showing original and added construction, facing
15	N-498	Facade and north side, facing SE
16	N-498	Facade, south side, and 1959 addition, facing E
17	N-498	1959 addition to south side, facing NE
18	N-1237	East side and rear, facing SW
19	N-1237	East side and rear, facing SW
20	N-1237	Facade and east side, facing N

			_
			-
			_
			-
,			_
			_
			_
			-
			_
			_
			_
			_
			_
			_
			_
			_
			<u> </u>
			_

## PHOTOGRAPHIC INVENTORY - CONTACT SHEET

Negative location (if other than SHPO)								
Photo Ro	II # <u>C-45</u>	37 Surveyor <u>Geral</u> d M. Kuncio Dat	e Sept. 2003					
Frame #	CRS#	CRS # Description of view						
21	N-1237	West side and rear, facing SE						
22	N-1237	Outbuildings, facing NW						
<b>່ 23</b>	N-1237	Barn, facade and east side, facing NW	_					
24	N-14150	Facade and north side, facing SE						
	_	<del></del>						
	1							
	_							
	<b>→</b> –							
			_					
	_							
	_							
		-						
doc # 20-06-	 -01-05-11	USE BLACK INK ONLY	crs - 12					

			-
			_
			_
			-
			-
			-
			_
			_
			-
			_
			_
			_
			_
			-
			<del>-</del> -
			_
 	<u> </u>	. <del></del>	 

#### PHOTOGRAPHIC INVENTORY - CONTACT SHEET

Negative location (if other than SHPO)

Photo Roll # C-4538 Surveyor Gerald M. Kuncio Date Sept. 2003

Frame #	CRS#	Description of view
1	N-498	Interior of the sanctuary from the rear, facing ⊟
2	N-498	Interior of the sanctuary from the rear, facing E
3	N-498	Interior of the sanctuary from the southeast corner, facing NW
4	N-498	Interior of the sanctuary from the altar, facing W
5	N-498	Interior of the sanctuary from the choir loft, facing E
6	N-498	Interior of the sanctuary from the choir loft, facing E
7	N-498	Interior of the first floor from the entrance, facing E
8	N-498	Interior of the first floor from the entrance, facing E
9	N-14150	Facade and north side, facing SE
10	N-1237	Barn, facade and east side, facing NW
11	N-1237	Barn, west side and rear, facing SE
12	N-1237	Garage, facade and west side, facing NE
13	N-1237	Barn, west side and rear, facing SE
14	N-14150	Interior of first floor from front to rear, facing E
15	N-14150	Interior of first floor from front to rear, facing NE
16	N-14150	Interior of first floor from front to rear, facing NE
17	N-14150	Interior of second floor from front to rear, facing E
I .		

		_
		_
		-
		-
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_
		_